

AIRWORTHINESS BULLETIN

Undercarriage Pin Circlip Damage - AWB 32-011 Issue: 1
Diamond DA42 Aircraft Date: 21 February 2008

1. Applicability

This AWB is applicable to all Diamond DA42 aircraft.

2. Purpose

The purpose of this AWB is to bring to the attention of Registered Operators and maintainers of Diamond DA42 aircraft that undercarriage pin circlips part number DIN471-08-2P are subject to fatigue failures which may lead to undercarriage failures.

3. Background

Two reports have been received indicating that the circlips part number DIN471-08-2P holding the main undercarriage pins in place have failed due to fatigue causing the pin to move to a position where the pin may fall out. There is no indication of this failure until the undercarriage becomes inoperative.

4. Recommendation

It is recommended that all Registered Operators of Diamond DA42 series aircraft;

- Inspect all main undercarriage pin circlips part number DIN471-08-2P for damage, fatigue and security as soon as practical.
- Inspect all main undercarriage pin circlips at every periodic inspection for security fatigue and damage.
- Replace all main undercarriage pin circlips which show signs of fatigue or damage.
- Replace all main undercarriage pin circlips at 200 hrs TIS intervals.
- Report all damaged or fatigued main undercarriage pin circlips to CASA through the normal SDR system.




AIRWORTHINESS BULLETIN

Undercarriage Pin Circlip Damage -Diamond DA42 Aircraft

32-011 **AWB** Issue:

Date: 21 February 2008



5. Enquiries

Enquiries with regard to the content of this Airworthiness Bulletin should be made via the direct link e-mail address:

AirworthinessBulletin@casa.gov.au

Or in writing, to:

Airworthiness Engineering Branch Civil Aviation Safety Authority GPO Box 2005, Canberra, ACT, 2601