

AIRWORTHINESS BULLETIN

Beechcraft King Air 200C Power Lever AWB 76-002 Issue: 1
Control Cable Breaking Date: 19 November 2007

1. Applicability

This AWB is applicable to all BEECHCRAFT KING AIR aircraft.

2. Purpose

The purpose of this AWB is to bring to the attention of all registered operators and maintenance personnel of BEECHCRAFT KING AIR aircraft that power lever control cables can fail due to corrosion.

3. Background

A recent report indicated that a right hand engine power lever control cable was found broken due to corrosion where the cable passed through the battery box area.

4. Recommendation

It is recommended that Registered Operators of BEECHCRAFT KING AIR aircraft:

- Inspect the power lever cables at the next periodic inspection for:
 - o damage
 - breakage and
 - o corrosion.
- Check the power levers for signs of binding, and if there is some binding the power lever cables should be inspected.
- Remove all damaged or corroded cables from service.
- Amend the System of Maintenance to include an inspection of the power lever cables at 500 hour intervals or at nearest periodic inspection.
- Report all incidents of corroded damaged or broken cables to CASA through the SDR system.



AIRWORTHINESS BULLETIN

Beechcraft King Air 200C Power Lever AWB 76-002 Issue: 1
Control Cable Breaking Date: 19 November 2007

5. Enquiries

Enquiries with regard to the content of this Airworthiness Bulletin should be made via the direct link e-mail address:

AirworthinessBulletin@casa.gov.au

Or in writing, to:

Airworthiness Engineering Branch Civil Aviation Safety Authority GPO Box 2005, Canberra, ACT, 2601