



CASA AD Biweekly 20/2015 – 1 October 2015

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 18 September 2015 and 1 October 2015.

Rotorcraft

AgustaWestland A109 Series Helicopters

2015-0190-E - Main Rotor - Blades - Inspection

Airbus Helicopters (Eurocopter) AS 350 and EC 130 Series Helicopters

2015-0195 - Tail Rotor Drive - Drive Shaft Bearings - Inspection / Replacement

Airbus Helicopters (Eurocopter) AS 355 Series Helicopters

AD/AS 355/67 Amdt 5 - Main Gearbox Lubrication Pump - CANCELLED

2015-0195 - Tail Rotor Drive - Drive Shaft Bearings - Inspection / Replacement

Airbus Helicopters Deutschland (Eurocopter) MBB-BK 117 Series Helicopters

2015-0198 - Power Plant - Engine Mount Bushings - Inspection

Airbus Helicopters (Eurocopter) EC 225 Series Helicopters

2015-0196-E - External Life Raft Jettison System / Inflation Cylinder Percussion System / Bellcrank - Inspection

Bell Helicopter Textron Canada (BHTC) 206A-1 (OH-58A) Series Helicopters

AD/OH-58/8 Amdt 1 - Main Rotor Mast Cracking

Hiller Aviation UH-12 Series Helicopters

2015-20-51 - Main Rotor Blade Fork TT retention pin hole - MPI

Below 5700 kgs

M7 Aerospace (Fairchild / Swearingen) SA226 and SA227 Series Aeroplanes

2015-19-10 - Elevator Control - Column Pivot Bearing, Control Rod & Bolt - Inspection / Replacement

Above 5700 kgs

Airbus A319, A320 and A321 Series Aeroplanes

2015-0191 (Correction) - Airplane Flight Manual - Section Normal Procedures / After Start - Amendment

Airbus A330 Series Aeroplanes

2015-0192 - Doors - Forward and Aft Cargo Compartment Doors - Inspection

2015-0194 - Fuel - Fuel Pumps - Inspection / Modification

2012-0034R1 - Landing Gear - Nose Landing Gear (NLG) Retraction Actuator - Overhaul
2015-0183R1 - Equipment / Furnishings - Passenger / Crew and Emergency Exit Door Slide and Slide Raft Attachments - Inspection

Airbus A380 Series Aeroplanes

2015-0136R1 - Stabilizers - Inboard and Outboard Elevators Hinge Lines - Inspection
2015-0188 - Air Conditioning - Electronic Centralized Aircraft Monitoring / Flight Warning System - Software Update / Aircraft Flight Manual Changes
2015-0197 - Fuselage - Frame 74 to 90 / Shim Sheet on Section 18.1 - Inspection / Repair

Boeing 737 Series Aeroplanes

2015-19-03 - Fuel Shutoff Valves (Spar Valve) - Airworthiness Limitation

Boeing 747 Series Aeroplanes

2015-19-06 - Integrated Display Units

Boeing 757 Series Aeroplanes

2015-19-04 - Fuel Shutoff Valves (Spar Valve) - Airworthiness Limitation

Boeing 767 Series Aeroplanes

2015-19-02 - Fuel Shutoff Valves (Spar Valve) - Airworthiness Limitation
2015-19-12 - Left and Right Stringer 37 between Body Stations (BS) 428 and 431 Lap Splices

Boeing 777 Series Aeroplanes

2015-19-01 - Fuel Shutoff Valves (Spar Valve) - Airworthiness Limitation

Boeing 787 Series Aeroplanes

2015-19-09 - Fuel Shutoff Valve (Spar Valve) Actuator - Replacement / Airworthiness Limitation

Bombardier CL-600 Series Aeroplanes

CF-2014-02R1 - Flight Controls - Rudder Control System - Cracking of the Pilot-Side Rudder Pedal Tubes
CF-2015-28 - Equipment/Furnishings - Damaged Decompression Window Louver Panel Assemblies and Detached Blowout Panels

Piston Engines

Technify Motors (Thielert) Piston Engines

2015-0189 - Time Limits / Maintenance Checks - Airworthiness Limitation Section - Amendment