



CASA AD Biweekly 3/2017 – 9 February 2017

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 27 January and 9 February 2017.

Rotorcraft

Airbus Helicopters (Eurocopter) AS 332 Series Helicopters

2017-0022 - Doors - Cabin Sliding Plug Doors / Emergency Jettisoning System - Inspection

Airbus Helicopters (Eurocopter) AS 350 and EC 130 Series Helicopters

2017-0020-E - Tail Rotor - Pitch Rod - Inspection

Airbus Helicopters (Eurocopter) AS 355 Series Helicopters

2017-0020-E - Tail Rotor - Pitch Rod - Inspection

Leonardo Helicopters (AgustaWestland) AB139 and AW139 Series Helicopters

2011-0205R1 (Correction) - Stabilizers - Tail Fin Assembly - Inspection / Replacement

2017-0011 - Tail Rotor - Tail Rotor Drive Shaft - Inspection / Modification

Robinson Helicopter Company R44 Series Helicopters

AD/R44/25 Amdt 2 - Main Rotor Blades - CANCELLED

Below 5700 kgs

Piper PA-31 Series Aeroplanes

2017-02-06 - Wiring Below Main Circuit Breaker Panel

Socata (Aerospatiale) TBM700 Series Aeroplanes

AD/TBM 700/27 Amdt 1 - Elevator Control System - CANCELLED

2017-0018 - Flight Controls - Aileron Control - Modification

Above 5700 kgs

328 Support Services Dornier 328 Series Aeroplanes

2017-0016 - Fuel - Fuel Line Clamps - Inspection / Replacement

Airbus A330 Series Aeroplanes

2017-0021 - Fuselage - Cabin and Cargo Compartments Parts - Inspection / Replacement

Airbus A380 Series Aeroplanes

2017-0013 - Wings - Flap Parts - Identification / Inspection [Wrong material]

2015-0141R3 - Wings - Leading Edge Shear Cleats - Inspection / Replacement

2017-0015 - Fuselage - Belly Fairing - Inspection / Repair / Replacement

Boeing 717 Series Aeroplanes

2017-01-03 - Airworthiness Limitations

Boeing 737 Series Aeroplanes

2017-02-05 - Skin Cracking Around aft Entry and aft Galley Doorways

Boeing 747 Series Aeroplanes

2017-02-04 - Cracking of Strut Side Skin and Spring Beam Support Fitting

Bombardier CL-600 Series Aeroplanes

CF-2017-06 - Rudder Controls - Yaw Damper Uncommanded Movement

CF-2016-20R1 - Equipment/Furnishings - Electrical Short of Bonding Jumper causing Burnt Water Supply Line and Smoke in Cabin

CF-2017-07 - Cold Weather Operations - Introduction of Low Temperature Ground Wing Anti-Ice System

Turbine Engines

Rolls Royce Deutschland Turbine Engines - Spey Series

2017-0014 - Engine - High Pressure Compressor Stage 12 Rotor Discs - Replacement [Life Limit]

Safran Helicopter Engines (Turbomeca) Turbine Engines - Arriel Series

2017-0019-E - Engine Fuel & Control - Drain Valve Assembly - Inspection / Replacement