



CASA AD Biweekly 3/2025 – 13 February 2025

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 31 January and 13 February 2025.

Rotorcraft

Airbus Helicopters (Eurocopter) AS 350 and EC 130 Series Helicopters

2025-0036 - Equipment / Furnishings - Cargo Hook Assembly - Inspection

Airbus Helicopters Deutschland (Eurocopter) MBB-BK 117 Series Helicopters

2025-0027 - Main Rotor - Swashplate Inner and Outer Ring Bolts - Inspection / Replacement

2025-0028 - Main Rotor - Main Rotor Head - Inspection / Re-identification

2025-0029 - Main Rotor - Swashplate - Inspection

Kawasaki BK 117 Series Helicopters

TCD-10411-2025 - Warning Unit - EMER OFF SW

Above 5700 kgs

Airbus A319, A320 and A321 Series Aeroplanes

2025-0030 - Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 - Damage Tolerant Airworthiness Limitations Items - Amendment

2025-0031 - Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 3 - Certification Maintenance Requirements - Amendment

2025-0032 - Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 4 - System Equipment Maintenance Requirements - Amendment

2025-0033 - Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 5 - Fuel Airworthiness Limitations - Amendment

2025-0037 - Aircraft Flight Manual - Amendment

Airbus A330 Series Aeroplanes

2025-0034 - Fire Protection - Engine Fire Extinguisher Bottles - Modification

Boeing 717 Series Aeroplanes

2025-02-07 - Loss of GPS Data or Degraded GPS Positional Accuracy while using certain Collins GLU-2100 Multi-mode Receivers - AFM Revision

Boeing 737 Series Aeroplanes

2025-02-02 - Inspection of the Frame Inner Chord and Web at STA 727

2025-02-07 - Loss of GPS Data or Degraded GPS Positional Accuracy while using certain Collins GLU-2100 Multi-mode Receivers - AFM Revision

Boeing 747 Series Aeroplanes

2025-02-05 - Improper Inner Diameter Grinding of Landing Gear Outer Cylinders

2025-02-07 - Loss of GPS Data or Degraded GPS Positional Accuracy while using certain Collins GLU-2100 Multi-mode Receivers - AFM Revision

2025-01-08 - Captain's and First Officer's Seats

Boeing 757 Series Aeroplanes

2025-02-07 - Loss of GPS Data or Degraded GPS Positional Accuracy while using certain Collins GLU-2100 Multi-mode Receivers - AFM Revision

2025-02-13 - Cracks at the Main Deck Cargo Door Cutout Forward and aft Hinge Attachment Holes

Boeing 767 Series Aeroplanes

2024-26-03 - Installation of Hoseducts around Potable Water Supply Hoses

2025-01-06 - Captain's and First Officer's Seats - Inspection

2025-02-07 - Loss of GPS Data or Degraded GPS Positional Accuracy while using certain Collins GLU-2100 Multi-mode Receivers - AFM Revision

Boeing 777 Series Aeroplanes

2025-02-07 - Loss of GPS Data or Degraded GPS Positional Accuracy while using certain Collins GLU-2100 Multi-mode Receivers - AFM Revision

Boeing 787 Series Aeroplanes

2025-01-09 - No. 1 Flight Compartment Windows - Replacement

Turbine Engines

Rolls Royce Deutschland Turbine Engines - RB211 TRENT 700 Series

2007-0260-CN - CANCELLED: Engine - Intermediate Pressure Turbine Bearing Oil Feed Tube - Inspection / Modification

Equipment

Restraint Equipment

2024-26-02 - Pacific Scientific Rotary Buckle Assembly P/N 1111430 and 1111475