



## CASA AD Biweekly 10/2014 – 15 May 2014

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 2 May 2014 and 15 May 2014.

### **Rotorcraft**

#### **Bell Helicopter Textron Canada (BHTC) 206 and Agusta Bell 206 Series Helicopters**

2014-0102-E - Tail Rotor - Tail Rotor Drive Shaft Line Nuts - Inspection / Replacement

#### **Bell Helicopter Textron and Agusta 412 Series Helicopters**

2014-0113-E - Main Rotor Drive - Engine-to-Transmission Drive Shaft Line Nuts - Inspection / Replacement

#### **Eurocopter AS 350 (Ecureuil) and EC 130 Series Helicopters**

2014-0114-E - Fuselage - Tail Boom / Fenestron Junction Frame - Inspection / Repair

### **Below 5700 kgs**

#### **DH 82 (Tiger Moth) Series Aeroplanes**

PAD/DH 82/18 - Inspection of Wooden Structure

#### **Fairchild (Swearingen) SA226 and SA227 Series Aeroplanes**

2014-09-02 - Aileron Control Cable Chain, Sprocket and Bearings - Replacement and Lubrication

### **Above 5700 kgs**

#### **Airbus Industrie A330 Series Aeroplanes**

2013-0267R1 (Correction) - Landing Gear - Main Landing Gear Bogie Beam - Inspection / Repair / Modification

2014-0010R1 - Wings - Centre Wing Box Keel Beam Fastener Holes at Frame 40 - Inspection

2014-0103 - Navigation - Angle Of Attack Probe Conic Plates - Operational Procedure / Replacement

2014-0120 - Landing Gear - Main Landing Gear Bogie Beam - Inspection / Repair

#### **AMD Falcon 50 and 900 Series Aeroplanes**

2014-0115 - Wings - Slat Extension Mechanical Stop Assembly - Modification

#### **Boeing 737 Series Aeroplanes**

AD/B737/224 Amdt 3 - Horizontal Stabiliser Attachment Pins and Bolts - Inspection

#### **Boeing 747 Series Aeroplanes**

AD/B747/298 Amdt 2 - Thrust Reverser System Locks

2014-09-08 - Fuselage Aft Tension Tie Channels - Inspection and Modification

### **Boeing 767 Series Aeroplanes**

AD/B767/123 - Fuel Tank Boost Pump and Override/Jettison Pump Wiring – CANCELLED  
2013-25-02 - Fuel Tank Boost Pump and Override/Jettison Pump Wiring  
2014-08-09 - Fuel Feed Boost Pump Pressure Loss

### **Boeing 777 Series Aeroplanes**

2014-09-06 - Low-Pressure Oxygen Hose

### **Dassault Aviation Falcon 2000 Series Aeroplanes**

2014-0115 - Wings - Slat Extension Mechanical Stop Assembly - Modification

### **Fokker F27 Series Aeroplanes**

AD/F27/159 - Fuel Tank Safety - Fuel Airworthiness Limitations - CANCELLED  
2014-0099 - Fuel Tanks - Modification [Fuel Tank Safety]  
2014-0100 - Fuel Tanks - Modification [Fuel Tank Safety]  
2014-0105 - Fuel Tanks - Modification [Fuel Tank Safety]

### **Fokker F28 Series Aeroplanes**

2014-0106 - Wing Fuel Tank - Modification [Fuel Tank Safety]  
2014-0107 - Main Fuel Tank Wiring - Modification [Fuel Tank Safety]  
2014-0108 - Fuel - Fuel Tanks - Modification [Fuel Tank Safety]  
2014-0109 - Fuel - Fuel Tanks - Modification [Fuel Tank Safety]  
2014-0110 - Fuel - Fuel Tanks - Modification [Fuel Tank Safety]  
2014-0111 - Fuel - Fuel Quantity Indication System - Inspection / Modification [Fuel Tank Safety]

## **Equipment**

### **Airconditioning Equipment**

AD/AIRCON/12 Amdt 4 - Kelly Aerospace Power Systems - Cabin Combustion Heaters

### **Emergency Equipment**

2014-0095R1 - Equipment/Furnishings - Crash Position Indicator - Modification & Aircraft Flight Manual - Amendment