



CASA AD Biweekly 17/2014 – 21 August 2014

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 8 August 2014 and 21 August 2014.

Rotorcraft

Bell Helicopter Textron Canada (BHTC) 429 Series Helicopters

CF-2014-28 - Time limits & Maintenance Checks - Airworthiness Life Limitations

Below 5700 kgs

DH 60 (Moth) Series Aeroplanes

AD/DH 60/9 - Lateral Fuselage Tie Rods - Removal and Replacement

DH 82 (Tiger Moth) Series Aeroplanes

AD/DH 82/18 - Inspection of Wooden Structure

DH 83 (Fox Moth) Series Aeroplanes

AD/DH 83/5 - Lateral Fuselage Tie Rods - Removal and Replacement

Robin Aviation Series Aeroplanes

2014-0185 - Air - Carburettor Heated Air Intake Duct - Modification

Above 5700 kgs

Airbus Industrie A319, A320 and A321 Series Aeroplanes

2014-0186 - Flight Controls - Flight Computers and Sharklet Common Ground Connection - Modification

Airbus Industrie A330 Series Aeroplanes

2014-0050R1 - Auto flight - Auto Pilot / Flight Director TCAS function - De-Activation

AMD Falcon 50 and 900 Series Aeroplanes

2014-0184 - Flight Controls - Aileron Servo Actuators - Replacement

Boeing 727 Series Aeroplanes

2014-16-09 - Replacement of Oxygen Hoses

Boeing 737 Series Aeroplanes

2014-16-09 - Replacement of Oxygen Hoses
2014-16-14 - Autothrottle Computer

Boeing 747 Series Aeroplanes

AD/B747/83 - Fuel Tank Access Doors - CANCELLED

Boeing 767 Series Aeroplanes

AD/B767/145 Amdt 2 - Airworthiness Limitations - CANCELLED

Bombardier BD-700 Series Aeroplanes

CF-2014-25 - Doors - Fuel Ingress into Aft Equipment Bay

Boeing 777 Series Aeroplanes

2014-15-21 - Thrust Reverser V-Blade Fitting Cracking

2014-16-11 - IFE Fire Protection

Bombardier (Canadair) CL-600 (Challenger) Series Aeroplanes

CF-2014-27 - Wings - Inboard Flap Hinge Box - Missing Fastener Head on Forward Attachment Fitting

CF-2013-39R1 - Wings - Inboard Flap Hinge Box - Missing Fastener Head on Forward Attachment Fitting

Dassault Aviation Falcon 2000 Series Aeroplanes

2014-0184 - Flight Controls - Aileron Servo Actuators - Replacement

Embraer ERJ-190 Series Aeroplanes

AD/ERJ-190/12 Amdt 1 - Hydraulic Shutoff Valves

Equipment

Supplementary Equipment

CF-2014-26 - Standard Practices - Helicopter External Transport System (HETS) - Unapproved Parts, Inadequate Service Life Limits and Maintenance Requirements