



Australian Government
Civil Aviation Safety Authority

CASA AD Biweekly 01/2026 – 15 January 2026

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 2 January 2026 and 15 January 2026.

Rotorcraft

Airbus Helicopters (Eurocopter) AS 332 Series Helicopters

2025-0278R1 - Equipment / Furnishings - Emergency Sea Anchor Pin - Inspection / Replacement

Airbus Helicopters H160 Series

2026-0001-E_Correction - Main Rotor - Main Rotor Pitch Rod End Bearings - Replacement

Airbus Helicopters (Eurocopter) EC 225 Series Helicopters

2025-0278R1 - Equipment / Furnishings - Emergency Sea Anchor Pin - Inspection / Replacement

Bell Helicopter Textron Canada (BHTC) 505 Series Helicopters

CF-2026-01 - Tail Rotor - Incorrect Tailcone Assembly Part Number (P/N) Identification Plate

Leonardo Helicopters (AgustaWestland) AB139 and AW139 Series Helicopters

2026-0003 - Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment

Leonardo Helicopters (AgustaWestland) AW189 Series Helicopters

2026-0004 - Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment

Below 5700 kgs

Diamond Aircraft Industries HK-36 Series Aeroplanes

2026-0006 - Doors - Canopy Jettison System - Inspection/Replacement

Above 5700 kgs

Airbus A350 Series Aeroplanes

2016-0074 - Exhaust - Thrust Reverser Actuation System - Replacement

2015-0241R2 - Flight Controls - Aileron Electro-Hydrostatic Actuator - Inspection / Replacement

2017-0093 - Fuselage - Potable Water Tank Brackets - Modification

2018-0008 - Wings - Main Landing Gear Trunnion Block Fuse Pin Retaining Pins - Inspection / Replacement

2018-0031 - Doors - Forward and Aft Cargo Door Frame Forks - Inspection

2018-0036 - Fuselage / Stabilizers - Interfay Sealant in Hybrid Joints - Modification

2018-0108 - Door - Passenger Doors Frameside Fittings - Modification

2018-0111R1 - Water/Waste - Forward Fuselage Shrouded Pipe T-Boxes and Clamps - Replacement

2018-0123 - Fuselage - Tail Cone Balancer Fitting Anchor Nuts and Fasteners - Modification

2018-0154 - Fire Protection - Engine Fire Extinguishing Pipes - Inspection

2018-0145R3 - Flight Controls - Elevators and Rudder Servocontrols - Replacement / Modification

2018-0178 - Hydraulic System / Fuel Tank Inerting System - Engine Driven Pump Rapid Overheat - Master Minimum Equipment List Restriction / Software Update / Modification

2018-0220 - Wings - Wing Rib Foot to Wing Lower Cover Clearance - Inspection / Temporary Operational Restrictions

2018-0243 - Doors - Bulk Cargo Door Hinge Arms - Modification

2018-0244 - Flight Controls - Flap / Slat Torque Shafts - Inspection / Replacement

2018-0246 - Pneumatic - Engine Bleed Air System - Modification Aircraft Flight Manual - Amendment

2018-0290 - Stabilizer - Vertical Stabilizer Tension Bolts - Modification

2019-0020 - Flight Controls - Slat Geared Rotary Actuators - Replacement

2019-0065 - Fuselage - Rear Fuselage Cone Diagonal Struts - Replacement

2019-0076 - Doors - Passenger Door Girt Bar Retention - Modification

2018-0058R2 - Flight Controls - Station Position Pick-Off Unit - Calibration Procedure

2019-0115 - Equipment / Furnishings - Baby Bassinet Inserts - Inspection / Modification

2019-0126 - Fuselage - Forward Cargo Door Upper Frame Fittings and Brackets - Inspection / Modification

2017-0129R1 - Integrated Modular Avionics - Internal Timer - Power Cycle (Reset)

2019-0175 - Power Plant - Engine Mounts and Thrust Links Washers - Inspection / Replacement

2019-0183 - Electric and Electronic Common Installation - Cargo Lining Gutter Assemblies - Modification

2019-0265 - Wings - Main Landing Gear Forward Pintle Bearing Lock Washer Tabs and Nuts - Inspection

2019-0181R1 - Fuselage - Forward and Aft Cargo Door Latch Fitting External Lugs - Inspection / Modification

2019-0301 - Flight Controls - Aileron and Elevator Electro-Hydrostatic Actuators - Modification Aircraft Flight Manual - Amendment

2020-0028 - Exhaust - Thrust Reverser Hinge Nut - Inspection / Replacement

2020-0027R1 - Flight Controls - Aileron, Elevator and Rudder Electro-Hydrostatic Actuators - Inspection / Replacement

2020-0060 - Exhaust - Pressure Relief Latch Access Doors - Modification

2020-0070 - Equipment / Furnishings - Emergency Locator Transmitter Protection - Modification

2020-0071 - Fuselage - Rear Cone Diagonal Struts - Inspection

2020-0109 - Fuselage - Frame 98 Flange Feet between Stringers 15 and 17 - Inspection / Modification

2020-0126 - Flight Controls - Flap Drive Struts and Lever Bearing Assemblies - Inspection

2020-0144 - Doors - Forward and Aft Cargo Door Retaining Rings - Inspection

2020-0155 - Communications / Cabin Systems - Removable Display Unit and Display Docking Station Attachment Interface - Operational Restriction / Inspection

2020-0166 - Fuselage - Seat Track Extremities - Inspection / Repair

2020-0203 - Indicating / Recording Systems - Integrated Control Panels - Modification ATA - Airplane Flight Manual - Abnormal / Normal Procedures Sections - Amendment

2020-0100R1 - Equipment / Furnishings - Cargo Compartment Lining Panels - Repair / Replacement

2018-0234R3 - Exhaust - Thrust Reverser Actuators - Greasing / Master Minimum Equipment List Restriction - Amendment

2021-0061 - Indicating / Recording Systems - Flight Warning System - Modification ATA - Aircraft Flight Manual - Ram Air Turbine Performance - Amendment

2021-0085 - Doors - Passenger Door Guide Arms - Replacement / Inspection / Modification

2021-0112 - Wings - Main Landing Gear Support Structure Fuse Pins - Inspection

2021-0127 - Landing Gear - Management System - Modification (Software Updates)

2021-0141 - Fuselage - Trimmable Horizontal Stabilizer Fittings and Bearing Assembly Attachment Interface - Inspection

2021-0161 - Landing Gear - Master Minimum Equipment List - Landing Gear Control - Amendment

2020-0167R1 - Flight Control and Guidance System - Ram Air Turbine Performance - Modification (Software Update) ATA 21 - Air Conditioning - Electrical Power Supply to Air Generation System Ram Air Actuators - Modification

2021-0220 - Flight Controls - Drive Struts on Flap Tracks 1 and 2 - Inspection / Replacement

2021-0269 - Fuselage - Ram Air Turbine Door / Belly Fairing Panels - Replacement

2021-0275 - Flight Controls - Slat Transmission Shafts / Slat Power Control Unit Torque Sensing Units - Inspection / Modification

2022-0013 - Equipment / Furnishings - Escape Slide-Raft at Passenger Doors 3 - Inflatable Free Aisle Restrictor - Modification / Replacement

2022-0014 - Equipment / Furnishings - Cockpit Seats - Inspection / Modification

2022-0015 - Wings - Wing Upper and Lower Covers - Inspection / Repair

2022-0031 - Pneumatic - Overheat Detection System Sensing Elements - Inspection - Master Minimum Equipment List - Temporary Operational Restrictions

2022-0054 - Aircraft Flight Manual - Performance Database - Amendment

2022-0065 - Fire Protection - Engine Fire Extinguishing Pipes - Inspection

2022-0088 - Hydraulic Power - Yellow Fire Shut Off Valve Grounding Wiring - Modification

2022-0093 - Fuselage - Fasteners at Frame 96 Stringer 6 and 7 on Right Hand Side - Inspection

2022-0098 - Aircraft Flight Manual - Section Limitations / Normal Procedures - Amendment ATA 27 - Flight Controls - Master Minimum Equipment List - Amendment / Primary Flight Control Computers - Modification (Software Update)

2022-0112 - Oxygen - Passenger Oxygen Masks - Replacement

2022-0119 - Air Conditioning - Forward Cargo Compartment Bracket Surface Protection - Modification

2022-0126 - Time Limits / Maintenance Checks - Certification Maintenance Requirements - ALS Part 3 - Amendment

2022-0156 - Pneumatic - Bleed Gimbals at Wing to Pylon Interfaces - Modification

2022-0157 - Fuel - Engine / Auxiliary Power Unit Low Pressure Shut-Off Valves and Auxiliary Power Unit Isolation Valve - Inspection / Replacement

2022-0183 - Fuselage - Belly Fairing Upper Wing Panel Fasteners - Inspection

2022-0186 - Fuselage - Overhead Storage Compartment Crash Rods - Inspection

2022-0211 - ATA 42 - Flight Control and Guidance System - Integrated Modular Avionics / Core Processing Input Output Modules - Modification (Software Update) / ATA 27 - Flight Controls - Primary Flight Control System - Modification (Software Update)

2022-0263 - Landing Gear - Main Landing Gear Bogie Pivot Pin - Greasing

2023-0026 - Nacelles / Pylons - Pylons Rib 1 - Inspection

2022-0217R1 - Hydraulic Power - Nose Landing Gear Pressure Return Lines - Replacement

2023-0051 - Doors - Main Landing Gear Doors / Axis Index Washer - Inspection

2023-0068 - Wings - Centre Wing Box Fasteners - Replacement

2023-0102 - Equipment / Furnishings - Lavatory Floor Fittings - Inspection

2021-0004R1 - Doors - Cockpit Escape Hatches - Replacement

2023-0162 - Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 5 - Fuel Airworthiness Limitations - Amendment

2023-0176 - Fuselage - Cargo Compartment Panels Sealing Tape - Inspection

2023-0196 - Electrical Power - Nickel-Cadmium Rechargeable Batteries - Replacement

2023-0215_Correction - Aircraft Flight Manual - Auto Flight System Control Panel ALT Outer Knob Use - Amendment ATA 22 - Auto Flight - Flight Control Unit - Modification

2024-0061 - Wings - Flaps - Flap Support Structure - Inspection

2024-0073 - Equipment / Furnishings - Galley Lower Attachment Studs - Inspection - Maintenance Task

2023-0132R1 - Wings - Inboard Flap Trunnion - Inspection / Modification

2024-0078 - Equipment / Furnishings - AFT Galley Complex Lower Attachment Studs - Inspection / Replacement

2024-11-01 - Electrical Power - Nickel-Cadmium Rechargeable Batteries - Replacement (Applies to FAA approved PMA parts only)

2024-0155 - Wings - RIB 1 Corner Fitting and Upper / Lower Wing Skin Cover Edge Glow Sealant - Inspection / Modification

2024-0156 - Landing Gear - Main Landing Gear Bogie Beam Axle - Replacement

2024-0157 - Flight Controls - Outer Aileron - Master Minimum Equipment List Restriction ATA 32 - Landing Gear - Remote Brake Control Unit / Main Wheel Tie Bolt / Steering Control - Master Minimum Equipment List Restriction

2024-0161 - Wings - Centre Wing Box Fasteners - Replacement

2024-0180 - Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 5 - Fuel Airworthiness Limitations - Amendment

2024-0186 - Oxygen - Crew Oxygen Cylinder Assembly - Inspection / Replacement

2024-0189 - Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 1 - Safe Life Airworthiness Limitations Items - Amendment

2024-0190_Correction - Aircraft Flight Manual - Normal Procedures - Amendment

2024-0220 - Oxygen - Cabin Oxygen Containers - Inspection

2024-0234 - Nacelles / Pylons - Pylons Rib 9 - Inspection

2024-0248 - Landing Gear - Nose Landing Gear Lower Torque Link - Replacement / Life Limitation

2025-0008 - Flight Controls - Flight Control Remote Module - Replacement / Life Limitation

2019-0207R2 - Doors - Passenger / Crew Door Girt Bar Fitting Assemblies - Inspection

2025-0073 - Stabilizers - Horizontal Tail Plane Lateral Load Fitting Bushings - Inspection

2025-0093 - Landing Gear - Nose Landing Gear Shock Absorber - Functional Check

2025-0100 - Engine Fuel and Control - Hydro-Mechanical Unit - Replacement / Modification

2025-0106 - Wings - Pylon Primary Structure - Inspection

2025-0105 - Aircraft Flight Manual - Derated Take-Off/Limitations - Amendment

2025-0117 - Fuselage - Bracket Supporting Flap Shaft Catcher - Inspection

2025-0120 - Cabin Systems - Antenna Adapter Plate - Inspection

2025-0089_C1 - Equipment / Furnishings - Forward of Door 4 Galleys Lower Attachment Studs - Inspection / Replacement

ATR-GIE Avions de Transport Regional ATR 42 Series Aeroplanes

2016-0046-CN - CANCELLED: Auto Flight - Auto Pilot and Yaw Damper - Operational Limitations / CANCELLED: Aircraft Flight Manual - Amendment

2019-0262-CN - CANCELLED: Flight Controls - Bonding Braid Screw and Pitch Tab Control Rod - Inspection / Repair

ATR-GIE Avions de Transport Regional ATR 72 Series Aeroplanes

2016-0046-CN - CANCELLED: Auto Flight - Auto Pilot and Yaw Damper - Operational Limitations / CANCELLED: Aircraft Flight Manual - Amendment

Bombardier BD-700 Series Aeroplanes

CF-2026-02 - Fuselage Structure - Aft Pressure Bulkhead Stiffener Found Cracked

Embraer ERJ 190 Series Aeroplanes

2026-01-01 - Operations in Freezing Fog

Embraer EMB-545 and EMB-550 Series Aeroplanes

2026-01-02 - FNC of the LH and RH HS Elevator Control System Backlash, and LH and RH Wing Aileron Control System Backlash

Saab 340 Series Aeroplanes

2026-0005 - Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment

Turbine Engines

General Electric Turbine Engines - GE90 Series

2025-25-07 - Replacement of Affected HPT Stage 1 and HPT Stage 2 Disks

International Aero Engines LLC (IAE) PW1100/PW1400 Series

2025-26-04 - Replacement of the Thermal Management System (TMS) Clevis Mounts