



Australian Government  
Civil Aviation Safety Authority

## CASA AD Biweekly 5/2021 – 11 March 2021

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 26 February and 11 March 2021.

### **Rotorcraft**

#### **Airbus Helicopters Deutschland (Eurocopter) EC 135 Series Helicopters**

2021-0066 - Equipment / Furnishings - Outboard Load System Fittings - Inspection / Re-identification

#### **Bell Helicopter Textron 205 Series Helicopters**

2021-04-19 - Tail Rotor Blade - Reduced Life Limit / Re-identification

#### **Bell Helicopter Textron Canada (BHTC) 505 Series Helicopters**

CF-2021-05R2 - Rotors Flight Control - Collective Controls - Failure of Pilot Collective Stick and Grip Assembly

#### **Leonardo Helicopters (AgustaWestland) A109 Series Helicopters**

2021-0065 - Electrical Power - Wiring Protection - Modification  
2021-0067 - Main Rotor Drive - Rotor Brake Control Cable - Inspection

#### **Leonardo Helicopters (AgustaWestland) AB139 and AW139 Series Helicopters**

2021-0054 - Equipment / Furnishings - Life Raft Reservoir and Actuator Cable - Replacement / Inspection

#### **Robinson Helicopter Company R66 Series Helicopters**

2021-04-12 - Tail Rotor Drive Shaft Assembly - Replacement

#### **Sikorsky Aircraft Corporation S-92 Series Helicopters**

2021-04-16 - Main and Nose Landing Gear Threaded Hinge Pins and Actuator Pins - Replacement

### **Below 5700 kgs**

#### **Grob Aircraft G115 Series Aeroplanes**

2021-0057-E - Flight Controls - Control Surface Hinge Bracket Attachment Bolts - Inspection

#### **Lancair Series Aeroplanes**

AD/LANCAIR/1 Amdt 1 - Canopy Latching

#### **Textron Aviation (Cessna) 208 Series Aeroplanes**

2021-04-10 - Elevator Torque Tube Attach Fasteners - Inspection

## **Above 5700 kgs**

### **Airbus A380 Series Aeroplanes**

2021-0051 (Correction) - Flight Controls - Rudder Electrical Backup Hydraulic Actuator and Elevator Servo Control Solenoid Valves - Replacement; and Master Minimum Equipment List / Airplane Flight Manual - Amendment  
2015-0197R1 - Fuselage - Frame 74 to 90 / Shim Sheet on Section 18.1 - Inspection / Repair  
2021-0063 - Oxygen - Steel Braided Polyurethane Flexible Hoses - Replacement

### **Boeing 777 Series Aeroplanes**

2021-06-03 - Potable Water System - Deactivation

### **Bombardier and MHI RJ Aviation CL-600 Series Aeroplanes**

CF-2021-06 - Ice and Rain Protection - Wing Anti-Ice (WAI) System - Wing Stall Prior to Touchdown due to Wing Leading Edge Icing

### **De Havilland Canada (Bombardier) DHC-8 Series Aeroplanes**

CF-2021-08 - Fuel System - Fuel Terminal - High Level Sensor Terminal Screw in Contact with Access Panel

### **Fokker Services F28 Series Aeroplanes**

2021-0059 - Wings - Front Spar Lower Boom - Inspection  
2021-0064 - Fuselage - Forward Pressure Bulkhead - Inspection

### **Fokker Services F100 (F28 Mk 100) Series Aeroplanes**

2021-0059 - Wings - Front Spar Lower Boom - Inspection  
2021-0064 - Fuselage - Forward Pressure Bulkhead - Inspection

### **Saab 340 Series Aeroplanes**

2021-0058 - Lights - Emergency Cabin Lighting Circuit Breaker 2LN - Replacement

### **Yabora Industria Aeronautica (Embraer) EMB-135 and EMB-145 Series Aeroplanes**

2021-02-02 (Correction) - Main Landing Gear Side Arm and Side Arm Strut - Inspection / Replacement

## **Piston Engines**

### **Austro Engine Piston Engines**

2021-0055R1 - Engine - Oil Pump - Replacement

## **Turbine Engines**

### **CFM International Turbine Engines - CFM56 Series**

2021-0062 - Engine - Low Pressure Turbine Rear Frames - Inspection / Replacement

### **GE Aviation Czech (Walter) Turbine Engines - M601, H75, H80 and H85 Series**

2021-0060 - Time Limits / Maintenance Checks - Airworthiness Limitations Section / 04-10 Limitations and 04-20 Inspections - Amendment

### **Rolls Royce Deutschland Turbine Engines - RB211 TRENT 900 Series**

2021-0056 - Engine - Low Pressure Turbine Seal Panel - Inspection / Replacement (Life Limitation)