



## CASA AD Biweekly 7/2021 – 8 April 2021

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 26 March and 8 April 2021.

### **Rotorcraft**

#### **Airbus Helicopters (Eurocopter) AS 332 Series Helicopters**

2021-0086 - Rotors Flight Control - Yaw Control Damper Support - Inspection / Replacement

#### **Leonardo Helicopters (AgustaWestland) A119 Series Helicopters**

2021-0096 - Rotors Flight Control - Collective Stick Torque Tube Assembly - Inspection / Replacement

#### **Leonardo Helicopters (AgustaWestland) AB139 and AW139 Series Helicopters**

2021-0095 - Placards and Markings - Stretcher Unit / Placard - Installation

#### **Sikorsky Aircraft Corporation EH-60, UH-60 and S-70 (All Variants) Series Helicopters**

2002-11-10 - Main Landing Gear Drag Beam - Inspection

2010-23-24 - Tail Rotor Gearbox Output Bevel Gear - Inspection

2012-22-14 - Intermediate Gearbox Internal Oil Passages

2012-23-13 (Correction) - Engine Oil Cooler, Main and Tail Rotor Blades, Tail Rotor Head, Tail Rotor Control System, Main Landing Gear Strut, Axle Truck, Fuel Transfer Valve, and Fasteners - Life Limits

2013-25-13 - Critical Parts - Life Limits

2013-26-13 - Gas Generator Turbine Rotor Parts - Life Limits

2020-02-17 - Tail Rotor Blade - Inspection

2020-22-19 - Main Rotor Blade Spindle Cuff - Inspection

### **Below 5700 kgs**

#### **Air Tractor AT-300, -400 and -500 Series Aeroplanes**

2021-05-14 - Flap Actuator Attachment Brackets

#### **Air Tractor AT-600 Series Aeroplanes**

2021-05-14 - Flap Actuator Attachment Brackets

### **Above 5700 kgs**

#### **Airbus A380 Series Aeroplanes**

2021-0087 - Engine Fuel & Control - Master Minimum Equipment List - Handling Bleed Valve Inoperative - Amendment

2021-0092 - Pneumatic - Cross-Bleed Ducts - Inspection / Replacement

#### **Air Tractor AT-800 Series Aeroplanes**

2021-05-14 - Flap Actuator Attachment Brackets

## **Boeing 737 Series Aeroplanes**

2021-07-02 - Pitot Anti-icing System

## **Boeing 747 Series Aeroplanes**

2021-06-10 - Operation with Inoperative Refuel Valves - Prohibition

## **Bombardier and MHI RJ Aviation CL-600 Series Aeroplanes**

CF-2021-13 - Ice and Rain Protection - Potable Water Line Ribbon Heater Fire Risk

## **De Havilland Canada (Bombardier) DHC-8 Series Aeroplanes**

CF-2021-11 - Pneumatic System - Wing Check Valve Bleed Air Leak

CF-2021-12 - Fire Protection System - Main Landing Gear (MLG) Primary Zone Advanced Pneumatic Detector (APD) Chafing Damage

## **Gulfstream Aerospace G-1159, G-IV and GV Series Aeroplanes**

2021-06-04 - Right Butt Line 6 Floor Beam Inboard Support Links and Bushings - Inspection

## **Piston Engines**

### **Austro Engine Piston Engines**

2021-0094 - Engine - Oil Pump - Replacement

## **Turbine Engines**

### **International Aero Engines AG (IAE) Turbine Engines - V2500 series**

2021-05-18 - Diffuser Case M-flange - Inspection / Replacement

### **Rolls Royce Deutschland Turbine Engines - RB211 TRENT 900 Series**

2018-0048R1 - Time Limits / Maintenance Checks - Engine Time Limits Manual - Amendment

### **Safran Helicopter Engines (Turbomeca) Turbine Engines - Arrius Series**

AD/ARRIUS/6 Amdt 1 - Engine Electronic Control Unit Software - CANCELLED

2021-0088 - Engine Fuel & Control - Digital Engine Control Unit - Software Update

## **Equipment**

### **Propellers - Variable Pitch - Hoffman**

2020-0226R1 - Propellers - Propeller Hub - Inspection / Replacement

### **Radio Communication (including Emergency Transmitters and Navigation Equipment)**

2021-05-17 - Rockwell Collins Flight Display System Application FDSA-6500 - AFM Revision / Placard Installation / Software Update - TCAS Flight Operations TA/RA Mode Prohibition

### **Restraint Equipment**

2021-07-13 - Pacific Scientific Rotary Buckle Assembly P/N 1111430 and 1111475

### **Supplementary Equipment (including Rescue Hoists)**

AD/SUPP/22 Amdt 2 - Lifesaving Systems D-Lok Hook - CANCELLED

2010-03-02 - Lifesaving Systems D-Lock Hook