



CASA AD Biweekly 9/2022 – 5 May 2022

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 22 April 2022 and 5 May 2022.

Rotorcraft

Airbus Helicopters (Eurocopter) AS 350 and EC 130 Series Helicopters

2022-0077-E - Rotors Flight Control - Flight Control Flexball Cables - Replacement

Airbus Helicopters (Eurocopter) AS 355 Series Helicopters

2022-0077-E - Rotors Flight Control - Flight Control Flexball Cables - Replacement

Airbus Helicopters Deutschland (Eurocopter) MBB-BK 117 Series Helicopters

2022-0077-E - Rotors Flight Control - Flight Control Flexball Cables - Replacement

Airbus Helicopters Deutschland (Eurocopter) EC 135 Series Helicopters

2022-0077-E - Rotors Flight Control - Flight Control Flexball Cables - Replacement

Airbus Helicopters (Eurocopter) EC 225 Series Helicopters

2022-0072 - Doors - VIP Flap Doors / Emergency Jettisoning System - Placard Installation

Below 5700 kgs

Piper PA-34 (Seneca) Series Aeroplanes

2022-09-13 - Drag Link to Nose Gear Trunnion Attachment Bolts - Life Limit

Textron Aviation (Beechcraft) 33 and 35-33 (Debonair/Bonanza) Series Aeroplanes

PAD/BEECH 33/41 Amdt 3 - Wing Bolt, Nut and Fitting

Textron Aviation (Beechcraft) 35 (Bonanza) Series Aeroplanes

PAD/BEECH 35/67 Amdt 3 - Wing Bolt, Nut and Fitting

Textron Aviation (Beechcraft) 36 (Bonanza) Series Aeroplanes

PAD/BEECH 36/43 Amdt 3 - Wing Bolt, Nut and Fitting

Textron Aviation (Beechcraft) 55, 58 and 95-55 (Baron) Series Aeroplanes

PAD/BEECH 55/79 Amdt 4 - Wing Bolt, Nut and Fitting

Textron Aviation (Beechcraft) 95 (Travelair) Series Aeroplanes

PAD/BEECH 95/26 Amdt 3 - Wing Bolt, Nut and Fitting

Above 5700 kgs

Airbus A380 Series Aeroplanes

2014-0213R1 - Fuselage - Section 19 Upper Cross Fitting Upper Beam Inner Cap Joints - Inspection

2022-0075 - Landing Gear - Body Landing Gear Rear Axle - Replacement

Boeing 737 Series Aeroplanes

2022-08-05 - Forward Main Cargo Deck Floor to RCB, Floor Panel Joints, Drain Troughs and Seat Track Splices - Inspection

Boeing 757 Series Aeroplanes

2022-07-07 - Passenger Service Units, Life Vest Panels and Video Panels - Installation of Lanyard Assemblies

Boeing 777 Series Aeroplanes

2022-06-07 - STA 2370 Pivot Bulkhead Forward Outer Chord, Longeron Fitting and Bulkhead Assembly Structure

Bombardier BD-700 Series Aeroplanes

CF-2022-25 - Landing Gear - Introduction of New Brake Accumulator Life Limit

Dassault Aviation Falcon 7X Series Aeroplanes

2022-0073 - Electrical Power - Direct Current Load Distribution / Right-Hand Front Secondary Power Distribution Box Feeder - Inspection / Modification

De Havilland Canada (Bombardier) DHC-8 Series Aeroplanes

CF-2022-21 - Stabilizers - Horizontal Stabilizer to Vertical Stabilizer Joint - Non-Conforming Saddle Washer (Radius Filler)

Embraer ERJ 170 Series Aeroplanes

2022-04-01 - Electrical Harnesses W126 and W127 - Inspection for Correct Routing

Embraer ERJ 190 Series Aeroplanes

2022-04-02 - Main Landing Gear Trunnion Bearing Attaching Parts - Inspection / Modification

Fokker Services F28 Series Aeroplanes

2022-0070 - Fuselage - Stubwing Bay Area Skin - Inspection

Fokker Services F100 (F28 Mk 100) Series Aeroplanes

2022-0070 - Fuselage - Stubwing Bay Area Skin - Inspection

Turbine Engines

Pratt and Whitney Canada Turbine Engines - PW300 Series

CF-2022-22 - Engine - Combustion Chamber Outer Case - Inadequate Fatigue Life of Forward Flange Bolts

Safran Helicopter Engines (Turbomeca) Turbine Engines - Arriel Series

2016-0004R1 - Engine Fuel & Control - Hydro-Mechanical Metering Unit - Inspection

Equipment

Emergency Equipment

G-2022-0009 - Equipment / Furnishings - Lifejackets - Inspection

Propellers - Variable Pitch - Hamilton Standard

2022-08-10 - Hamilton Sundstrand 54H Propellers - Propeller Blade - Inspection / Replacement