

# CASA AD Biweekly 15/2025 - 31 July 2025

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 18 July and 31 July 2025.

## Rotorcraft

# Airbus Helicopters (Eurocopter) AS 350 and EC 130 Series Helicopters

2025-0159 - Placards and Markings - Unlock Sliding Door - Installation

# Airbus Helicopters (Eurocopter) AS 355 Series Helicopters

2025-0159 - Placards and Markings - Unlock Sliding Door - Installation

# Airbus Helicopters Deutschland (Eurocopter) MBB-BK 117 Series Helicopters

2025-0153 - Equipment / Furnishings - Cargo Common Hook Beam - Modification

#### Airbus Helicopters (Eurocopter) EC 120 Series Helicopters

2025-0159 - Placards and Markings - Unlock Sliding Door - Installation

#### Leonardo Helicopters (AgustaWestland) AB139 and AW139 Series Helicopters

2025-0163 - Rotors Flight Control - Brake Pedal Assembly - Inspection

## Leonardo Helicopters (AgustaWestland) AW189 Series Helicopters

2025-0163 - Rotors Flight Control - Brake Pedal Assembly - Inspection

### Below 5700 kgs

# Daher Aerospace (Socata / Aerospatiale) TB 9 & TB 10 (Tobago) Series Aeroplanes

2025-0160 - Flight Controls - Lower Rudder Hinge Fitting - Inspection

#### Daher Aerospace (Socata / Aerospatiale) TB 20 (Trinidad) Series Aeroplanes

2025-0160 - Flight Controls - Lower Rudder Hinge Fitting - Inspection

## Daher Aerospace (Socata / Aerospatiale) TB 200 Series Aeroplanes

2025-0160 - Flight Controls - Lower Rudder Hinge Fitting - Inspection

# Extra Aerobatic Aircraft - Extra NG

2025-0156 - Placards and Markings - Modification - Aircraft Flight Manual - Amendment

#### Above 5700 kgs

# Airbus A319, A320 and A321 Series Aeroplanes

2025-0158 - Landing Gear - Main Landing Gear Door Actuators - Inspections

2025-0075R1 - Flight Controls - Part(s) Installation - Oxygen - Part(s) Installation - Pneumatic - Part(s) Installation

2025-0151R1 - Equipment / Furnishings - Escape Slide Inflation Reservoir Regulator Valve - Inspection / Modification

2025-0166 - Fuselage - Inner Cap and Frame Flange at Frame 68 Stringer 22 – Inspections

# **Airbus A330 Series Aeroplanes**

2025-0164 - Powerplant - Nacelle Inlet Cowl - Inspection

# **Airbus Canada BD-500 Series Aeroplanes**

CF-2025-37 - Fuel - Fuel Boost Pump - Loose Fasteners and Missing Brush Seal

# **Boeing 737 Series Aeroplanes**

2025-15-01 - Frame Web Crack Inspection

# **Boeing 747 Series Aeroplanes**

2025-15-07 - Captain's and First Officer's Seats

# **Embraer ERJ 190 Series Aeroplanes**

2025-07-02 - Airworthiness Limitations - Maintenance Review Board Report revision E2025-07-03 - Engine Feed Check Valve Failure

# **Turbine Engines**

# **General Electric Turbine Engines - CF34 Series**

2025-14-03 - Cracks in High Pressure Turbine Front Rotating Air Seal