



**Australian Government**  
**Civil Aviation Safety Authority**

## **CASA AD Biweekly 17/2019 – 22 August 2019**

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 9 August and 22 August 2019.

### **Rotorcraft**

#### **Airbus Helicopters (Eurocopter) AS 332 Series Helicopters**

2019-0195 - Tail Rotor - Hub Assembly - Inspection / Replacement

#### **Airbus Helicopters Deutschland (Eurocopter) MBB-BK 117 Series Helicopters**

2019-0198 - Flight Controls - Wiring Harness - Modification

#### **Airbus Helicopters Deutschland (Eurocopter) EC 135 Series Helicopters**

2019-0199 - Tail Rotor Drive - Ti-Bolt - Inspection/Replacement

#### **Leonardo Helicopters (AgustaWestland) A119 Series Helicopters**

2019-0194-E - Tail Rotor - Tail Rotor Duplex Bearing and Plug - Inspection

#### **Sikorsky Aircraft Corporation S-76 Series Helicopters**

AD/S-76/66 Amdt 1 - Main Landing Gear Positioning Rod Assembly

### **Below 5700 kgs**

#### **Textron Aviation (Cessna) 525 Series Aeroplanes**

2019-0086R1 - Flight Controls - Active Technology Load Alleviating System (EASA STC 10056170) - Deactivation / Modification; and Airplane Flight Manual Supplement - Amendment

### **Above 5700 kgs**

#### **Airbus A319, A320 and A321 Series Aeroplanes**

2019-0196 - Fuselage - Cabin, Cargo Compartment and Airframe Parts - Inspection / Replacement [Improper Heat Treatment]

2019-0197 - Fuel - Fuel Level Sensor Support Bracket - Replacement

#### **Airbus A380 Series Aeroplanes**

2019-0205 - Pneumatic - Engine Bleed Air System Certification Maintenance Requirements Task - Amendment

#### **Boeing 737 Series Aeroplanes**

2019-14-12 - Main Slat Track Assemblies

2019-14-15 - Fuselage - Stub Beams and Stub Beam Webs

2019-15-07 - Fuselage Lower Lobe Frames

## **Boeing 767 Series Aeroplanes**

2019-14-13 - Captain's and First Officer's Seats

## **Dassault Aviation Falcon 7X Series Aeroplanes**

2008-0221-CN - CANCELLED: Time Limits / Maintenance Checks - Airworthiness Limitations Section  
Chapter 5-40 - Amendment

## **Dassault Aviation Mystere-Falcon 20 and 200 and Fan Jet Falcon Series Aeroplanes**

2008-0221-CN - CANCELLED: Time Limits / Maintenance Checks - Airworthiness Limitations Section  
Chapter 5-40 - Amendment  
2019-0200 - Time Limits / Maintenance Checks - Airworthiness Limitations Section Chapter 5-40 -  
Amendment  
2019-0201 - Pneumatic - Engine Bleed Air System Certification Maintenance Requirements Task -  
Amendment

## **Dassault Aviation Mystere-Falcon 50 and 900 and Falcon 900EX Series Aeroplanes**

2008-0221-CN - CANCELLED: Time Limits / Maintenance Checks - Airworthiness Limitations Section  
Chapter 5-40 - Amendment

## **Dassault Aviation Falcon 2000 Series Aeroplanes**

2008-0221-CN - CANCELLED: Time Limits / Maintenance Checks - Airworthiness Limitations Section  
Chapter 5-40 - Amendment

## **Turbine Engines**

### **International Aero Engines AG (IAE) V2500 series**

2019-16-01 - Turbine Exhaust Case

### **Pratt and Whitney Canada Turbine Engines - PT6A Series**

CF-2019-30 - Compressor Turbine (CT) Blade Fracture due to Non-conforming CT Vane Installation