



CASA AD Biweekly 17/2011 - 25 August 2011

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 12 August and 25 August 2011.

Rotorcraft

Eurocopter SA 360 and SA 365 (Dauphin) Series Helicopters

2011-0154 - Rotor Flight Controls - Collective Pitch Lever Restraining Tab - Inspection / Adjustment

Kawasaki BK 117 Series Helicopters

TCD-7916-2011 - Cockpit and Cabin Door Outside Handles

Below 5700 kgs

De Havilland DHC-1 (Chipmunk) Series Aeroplanes

AD/DHC-1/41 Amdt 1 - Fuselage Rear Bulkhead - Inspection and Modification

AD/DHC-1/43 Amdt 1 - Engine Primer Pipe and Fuel Tank Selector Guide - Modifications, Inspections and Replacements

AD/DHC-1/44 Amdt 1 - Mandatory Modifications, Inspections and Replacements

Fairchild (Swearingen) SA226 and SA227 Series Aeroplanes

2011-17-07 - Primary Flight Control Cables

Above 5700 kgs

Airbus Industrie A319, A320 and A321 Series Aeroplanes

2010-0165-CN - Oxygen System - Passenger Oxygen Masks - Identification / Modification / Replacement

Airbus Industrie A380 Series Aeroplanes

2011-0058R2 (Correction) - Pneumatic - Pylon Bleed Duct - Inspection / Replacement

2011-0151 - Wings - Wing Flap Track 1 Aft Z-Link (Second Load Path) Lower Attachments - Inspection / Repair

Avions de Transport Regional ATR 42 Series Aeroplanes

AD/ATR 42/26 Amdt 1 - Windows - Cockpit Forward Side Windows

Bombardier (Canadair) CL-600 (Challenger) Series Aeroplanes

CF-2011-30 - Cracking on the Forward Face of the Rear Pressure Bulkhead Web

CF-2011-33 - Engine Support Beam - Cracking on the Upper and Lower Web

Bombardier (Boeing Canada/De Havilland) DHC-8 Series Aeroplanes

CF-2011-34 - Ice Protection System - Failure of the Timer and Monitor Unit
CF-2011-31 - Incorrect Heat Treatment of Pushrod Assembly
CF-2011-32 - Rudder Control - Excessive Wear on the Brake Pedal Bellcrank

Fokker F100 (F28 Mk 100) Series Aeroplanes

AD/F100/30 Amdt 1 - Flight Warning Computer Replacement

Piston Engines

Thielert Piston Engines

2011-0152-E - Engine - Clutch Assembly - Identification / Replacement

Turbine Engines

AlliedSignal (Garrett/AiResearch) Turbine Engines - TPE 331 Series

2011-18-51 - PMA Main Shaft Bearings

General Electric Turbine Engines - CF6 Series

2011-18-01 - Fluorescent Penetrant Inspection (FPI) of the Stage 3 Low-pressure Turbine (LPT)

General Electric Turbine Engines - CF34 Series

2011-18-02 - Replacement of Fan Rotor Blade Retainers and Fan Rotor Spinner Support