



CASA AD Biweekly 15/2012 – 26 July 2012

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 12 July and 26 July 2012.

Lighter Than Air

Gas Balloons

2012-0130-E - Standard Practices and Structure - General - Envelope Rip Panel - Inspection

Rotorcraft

Agusta AB139 and AW139 Series Helicopters

2012-0076R1 - Tail Rotor - Tail Rotor Blades - Inspection / Replacement

Eurocopter AS 332 (Super Puma) Series Helicopters

AD/S-PUMA/85 Amdt 1 - Main Rotor Drive - Epicyclic Reduction Gear Module - CANCELLED

2012-0129-E - Main Rotor Drive - Main Gear Box, Intermediate gear Box and Tail Gear Box - Modification / Inspection

Eurocopter EC 225 Series Helicopters

AD/EC 225/12 Amdt 1 - Main Rotor Drive - Epicyclic Reduction Gear Module - CANCELLED

2012-0129-E - Main Rotor Drive - Main Gear Box, Intermediate gear Box and Tail Gear Box - Modification / Inspection

Sikorsky S-92 Series Helicopters

2012-14-08 - MGB Housing Cored Passage Cracking

Below 5700 kgs

Airparts (NZ) Ltd. FU 24 Series Aeroplanes

DCA/FU24/181 - Horizontal Stabiliser Electric Trim System - Installation

Above 5700 kgs

Airbus Industrie A319, A320 and A321 Series Aeroplanes

2012-0133 - Fuel System - Centre Tank Fuel Pump Control Circuit - Modification

2012-0134 - Equipment / Furnishing - 80VU Rack Attachments - Inspection / Repair / Replacement

2012-0132 - Fuselage - Forward Fuselage Frame (FR) 24 Circumferential Junction - Inspection / Repair

Airbus Industrie A380 Series Aeroplanes

2012-0135 - Oxygen - Crew Oxygen / Rod Fitting and Cylinder Brackets of Oxygen Box and Reverse Z Stop Fitting Screws – Modification

Boeing 737 Series Aeroplanes

AD/B737/197 Amdt 3 - Flight Control Modules (FCM) - Replacement

AD/B737/228 Amdt 1 - Honeywell Start Converter Unit

Boeing 747 Series Aeroplanes

2012-13-09 - Windshield Terminal Block Inspection

Boeing 767 Series Aeroplanes

2012-14-02 - Thrust Reverser Deactivation Pin - Replacement

Boeing 777 Series Aeroplanes

2012-12-08 correction - Fuse Pin - MLG Retract Actuator - Inspection / Replacement

2012-13-05 - Low Pressure Oxygen Hoses

2012-14-03 - Fatigue Crack - Lap Joint - Inspection / Repair

British Aerospace BAe 146 Series Aeroplanes

2012-0136 - Wings - Forward Engine Pylon Pick-up Brackets - Inspection / Repair

Gulfstream (Grumman) G1159 and G-IV Series Aeroplanes

2012-13-12 - Paint Thickness - Flight Control Surfaces - Inspection

Equipment

Parachute Equipment

UF-2012-003 - AERAZUR - Pickable Textile Reserve Handle

Radio Communication and Navigation Equipment

2012-14-15 - Honeywell KGS200 WAAS GNSSU