



CASA AD Biweekly 2/2012 – 26 January 2012

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 13 January and 26 January 2012.

Rotorcraft

Agusta A109 Series Helicopters

2011-0236 (Correction) - Landing Gear - Main Landing Gear (MLG) Actuator Bracket Attachment Bolts
- Replacement / Inspection

Below 5700 kgs

Beechcraft 33 and 35-33 (Debonair/Bonanza) Series Aeroplanes

AD/BEECH 33/48 - Beechcraft Forward Elevator Cable - Replacement

Beechcraft 35 (Bonanza) Series Aeroplanes

AD/BEECH 35/74 - Beechcraft Forward Elevator Cable - Replacement

Beechcraft 36 (Bonanza) Series Aeroplanes

AD/BEECH 36/54 - Beechcraft Forward Elevator Cable - Replacement

Beechcraft 50 (Twin Bonanza) Series Aeroplanes

AD/BEECH 50/34 - Beechcraft Forward Elevator Cable - Replacement

Beechcraft 55, 58 and 95-55 (Baron) Series Aeroplanes

AD/BEECH 55/98 - Beechcraft Forward Elevator Cable - Replacement

Beechcraft 56TC (Turbo Baron) Series Aeroplanes

AD/BEECH 56/36 - Beechcraft Forward Elevator Cable - Replacement

Fairchild (Swearingen) SA226 and SA227 Series Aeroplanes

AD/SWSA226/43 Amdt 7 - Supplemental Inspection Program and Life Limited Items

Above 5700 kgs

Airbus Industrie A319, A320 and A321 Series Aeroplanes

AD/A320/147 Amdt 2 - Life Limited and Monitored Parts - CANCELLED
2012-0008 - Time Limits and Maintenance Checks - Safe Life Airworthiness Limitation Items - ALS Part 1 - Amendment
2012-0012 - Flight Controls - Flap Interconnecting Strut - Identification / Modification / Replacement

Airbus Industrie A330 Series Aeroplanes

2012-0009 - Flight Controls - Spoiler Servo Controls (SSC) - Identification / Operational Test

Airbus Industrie A380 Series Aeroplanes

2012-0010 - Indicating & Recording Systems - Flight Data Recording System (FDRS) - Software Installation
2012-0011 - Auxiliary Power Unit (APU) Air Intake Duct Access Cover Cut-Out - Inspection / Repair
2012-0013 - Wings - Wing Rib Foot - Inspection

Airbus Industrie A330 Series Aeroplanes

2012-0015 - Flight Controls - Flap Interconnecting Strut - Identification / Modification / Replacement

Boeing 767 Series Aeroplanes

2011-25-05 - Main Fuel Tank Boost Pumps and Center Auxiliary Tank Override & Jettison Pumps

Bombardier (Boeing Canada/De Havilland) DHC-8 Series Aeroplanes

CF-2012-04 - Hydraulic Accumulators - Screw Cap/End Cap Failure
CF-2012-05 - Chafing of the Wire Harness at the Wing Leading Edge

British Aerospace BAe 146 Series Aeroplanes

2012-0004 - Time Limits / Maintenance Checks - Airworthiness Limitations - Amendment / Implementation

Piston Engines

Teledyne Continental Motors Piston Engines

AD/CON/60 Amdt 4 - Fuel Injection Supply Lines

Turbine Engines

General Electric Turbine Engines - CF34 Series

2012-01-10 - CVD Support Assembly Removal From Service and Determination of Fan Drive Shaft Serviceability