



## CASA AD Biweekly 11/2013 – 30 May 2013

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 17 May 2013 and 30 May 2013.

### **Rotorcraft**

#### **Eurocopter EC 135 Series Helicopters**

2009-0272 - Main Rotor - Sliding Sleeve - Pre-Flight Check Amendment

#### **Eurocopter EC 225 Series Helicopters**

2013-0113-E - Rotor Drive - Main Gearbox Emergency Lubrication System / Rotorcraft Flight Manual  
Emergency Procedures - Amendment

### **Below 5700 kgs**

#### **Aerospatiale (Socata) TBM 700 Series Aeroplanes**

AD/TBM 700/20 Amdt 2 - Flap Attachment Fittings - Flap Carriages - CANCELLED  
AD/TBM 700/35 - Flight Controls - Flap Actuator - CANCELLED  
2013-0104R1 - Flight Control - Flap Actuator - Inspection / Replacement  
2013-0105 - Wings - Flap Carriages - Modification / Inspection / Replacement

#### **Beechcraft 200 (Super King Air) Series Aeroplanes**

AD/BEECH 200/38 Amdt 6 - Wing Front Spars

#### **Consolidated Aeronautics, Colonial and LA-4 Series Aeroplanes**

AD/LA-4/25 Amdt 2 - Horizontal and Vertical Stabiliser Attachment Fitting - CANCELLED

#### **Pilatus PC-12 Series Aeroplanes**

2013-0114 - Navigation - Electronic Standby Instrument System / Power Return Wires - Modification

### **Above 5700 kgs**

#### **Airbus Industrie A380 Series Aeroplanes**

2013-0108 - Wings - Wing Rib Feet - Modification

#### **Boeing 737 Series Aeroplanes**

AD/B737/181 Amdt 1 - Flap Track Assembly and Rear Spar Attachments - CANCELLED  
AD/B737/213 - Fuselage Lap Joints - CANCELLED  
AD/B737/262 Amdt 1 - Wing Outboard Flap Inboard Flap Track - CANCELLED  
2013-09-08 (Correction) - Fuel System - Engine Fuel Suction Feed  
2013-09-10 - Forward Cargo Door Frame - Inspection / Modification

#### **Bombardier (Canadair) CL-600 (Challenger) Series Aeroplanes**

CF-2013-13 - Rudder Controls - Yaw Damper Uncommanded Movement

## **Bombardier (Boeing Canada/De Havilland) DHC-8 Series Aeroplanes**

CF-2011-01R2 - Main Landing Gear Alternate Extension System - Cam Mechanism not in Normal Rested Position

CF-2013-09R1 - Fuel System - Insufficient Clearance Between Fuel Line and Structure

## **Fokker F28 Series Aeroplanes**

2013-0112 - Airplane Flight Manual - Erroneous Radio Altimeter Indication Abnormal Procedure - Introduction & Navigation - Radio Altimeter Circuit Breakers - Modification

## **Fokker F100 (F28 Mk 100) Series Aeroplanes**

2013-0112 - Airplane Flight Manual - Erroneous Radio Altimeter Indication Abnormal Procedure - Introduction & Navigation - Radio Altimeter Circuit Breakers - Modification

## **Gulfstream Aerospace G150 Series Aeroplanes**

01-12-02-02R1 - Aircraft Flight Manual (AFM) - Update

## **Piston Engines**

### **Thielert Piston Engines**

2013-0109 - Engine - Crankcase Assembly Opening - Sealing

## **Turbine Engines**

### **General Electric Turbine Engines - GE90 Series**

2013-10-52 - Transfer Gearbox (TGB) Radial Gear Cracking and Separation

### **Rolls Royce Germany Turbine Engines - BR700 Series**

2013-0110 - Engine Fuel and Control - Spill Return to Fuel Pump Tube - Replacement

### **Turbomeca Turbine Engines - Astazou Series**

2013-0111 - Engine - Second Stage Turbine Disc - Replacement

## **Equipment**

### **Electrical Equipment**

2013-10-01 - Spectrolab Nightsun XP Searchlab (Replaces EASA AD 2010-0237R2)