



## CASA AD Biweekly 2/2013 – 24 January 2013

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 11 January and 24 January 2013.

### **Rotorcraft**

#### **Agusta A109 Series Helicopters**

2013-0009 - Tail Rotor - Blade Retaining Bolts - Inspection / Replacement

#### **Agusta A119 Series Helicopters**

2013-0009 - Tail Rotor - Blade Retaining Bolts - Inspection / Replacement

#### **Eurocopter BO 105 Series Helicopters**

AD/BO 105/16 Amdt 1 - Tension-Torsion Strap - CANCELLED

AD/BO 105/21 - Tension-Torsion Strap - 2 - CANCELLED

2013-0015 - Time Limits and Maintenance Checks - Airworthiness Limitation Items - Amendment

### **Below 5700 kgs**

#### **Cessna 400 Series Aeroplanes**

AD/CESSNA 400/119 - Airframe Life Limitation

#### **Diamond DA40 Series Aeroplanes**

2013-0018 - Turbo Charger - Intercooler Installation / Charged Air Tubing - Inspection / Modification

#### **Grob G115 Series Aeroplanes**

2013-0017 - Instruments - Control Panel Main Cable Loom Routing - Inspection

#### **TECNAM P92, P96, and P2002 Series Aeroplanes**

2013-0019 - Stabilizers - Stabilator Trim Tab Hinge Supports - Inspection

### **Above 5700 kgs**

#### **Airbus Industrie A319, A320 and A321 Series Aeroplanes**

2013-0011 - Windows - Cockpit Sliding Window Seals - Inspection / Modification

#### **Airbus Industrie A330 Series Aeroplanes**

AD/A330/81 - Frame 53.3 Circumferential Joint - CANCELLED

#### **Airbus Industrie A380 Series Aeroplanes**

2013-0005 - Landing Gear - Body Landing Gear Retraction Actuator Pin Collar - Replacement

2013-0006 - Oxygen - Passenger Oxygen Rigid Pipe - Inspection / Replacement / Modification

### **Airbus Industrie A330 Series Aeroplanes**

2011-0171R1 - Fuselage - Frame (FR) 40 / Fuselage Skin Panel Junction - Inspection  
2013-0016 - Fuselage - Frame 53.3 Circumferential Joint - Reinforcement

### **Boeing 737 Series Aeroplanes**

AD/B737/240 - Flight Control Computer Software - CANCELLED  
2013-01-03 - Arcing in Seat Electronic Boxes

### **Boeing 747 Series Aeroplanes**

2012-25-13 - Main Deck Side Cargo Door - Latch Pins - Inspection and Modification  
2013-01-02 - Control switches, Forward, Aft and Nose Cargo Doors

### **Bombardier (Canadair) CL-600 (Challenger) Series Aeroplanes**

CF-2013-01 - Crew Oxygen System - Oil Contamination

### **Embraer ERJ-170 Series Aeroplanes**

2013-01-01 - Wing Spar 2 - Inspection

### **Fokker F28 Series Aeroplanes**

2013-0010 - Engine Controls - Thrust Control Setting Adjustment - Inspection

### **Fokker F100 (F28 Mk 100) Series Aeroplanes**

2013-0010 - Engine Controls - Thrust Control Setting Adjustment - Inspection

## **Turbine Engines**

### **Pratt and Whitney Canada Turbine Engines - PW100 Series**

CF-2013-02 - First Stage Power Turbine Blade Failure

### **Rolls Royce Turbine Engines - Tay Series**

2013-0007 - Engine - Low Pressure Turbine Discs at Stage 2 and 3 - Inspection - Replacement

### **Rolls Royce Turbine Engines - RB211 TRENT 900 Series**

2012-0057R1 - Engine - Intermediate Pressure Shaft Coupling - Inspection / Replacement

### **Turbomeca Turbine Engines - Arriel Series**

2012-0124R1 - Engine - Module M03 (Gas Generator) - Turbine Blade - Modification

## **Equipment**

### **Turbochargers**

2012-24-09 (Correction) - Hartzell Turbocharger Turbine Wheel Removal