



CASA AD Biweekly 4/2014 – 20 February 2014

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 7 February 2014 and 20 February 2014.

Rotorcraft

Agusta A109 Series Helicopters

2014-0037 - Main Rotor Drive - Engine to Transmission Drive Shaft Nuts - Inspection / Replacement

Bell Helicopter Textron 204 Series Helicopters

2014-03-11 - Tail Rotor Cable Assembly

Bell Helicopter Textron and Agusta 412 Series Helicopters

2014-0040-E - Tail Rotor Drive - Flanged Adapter - Inspection / Replacement

Bell UH-1 Series Helicopters

2014-03-10 - Tail Rotor Cable Assembly

Above 5700 kgs

Airbus Industrie A380 Series Aeroplanes

2013-0089R1 - Hydraulic Power - Hydraulic Power Accumulator - Replacement

2013-0266R1 - Wings - Cruciform Fitting Frame 56 - Inspection / Modification

Boeing 737 Series Aeroplanes

2014-01-05 - Stringer Splice Cracks, Butt Strap Cracks and Vertical Chem Mill Fuselage Skin Cracks

Bombardier (Canadair) CL-600 (Challenger) Series Aeroplanes

CF-2014-10 - Main Landing Gear - Brake Hydraulic Line - Incorrect Connection

Bombardier (Boeing Canada/De Havilland) DHC-8 Series Aeroplanes

CF-2014-08 - Forward Translating Door - Loose Bolts

CF-2014-11 - Landing Gear - False Emergency Downlock Indication

Dassault Aviation Falcon 2000 Series Aeroplanes

2012-0081R1 - Airplane Flight Manual - Take-Off Under Out-Of-Trim Condition - Operational Limitation

Embraer ERJ-190 Series Aeroplanes

2014-02-01 - Replacement of Low-Stage Bleed Check Valves

Learjet 60 Series Aeroplanes

2013-24-04 - Fuel Cross Flow Tube

Turbine Engines

Pratt and Whitney Canada Turbine Engines - PW100 Series

CF-2014-09 - Engine High Pressure Fuel Line Fretting

Rolls Royce Germany Turbine Engines - BR700 Series

2012-0230R1 - Engine - High Pressure Compressor Rotor Disc Assembly - Removal

Turbomeca Turbine Engines - Arriel Series

2014-0036 - Engine - Accessory Gear Box (M01) - 41/23 Tooth Bevel Gear Assembly - Check / Replacement