



CASA AD Biweekly 25/2014 – 11 December 2014

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 28 November 2014 and 11 December 2014.

Rotorcraft

Airbus Helicopters (Eurocopter) AS 332 Series Helicopters

2014-0263 - Doors - Cabin Sliding Plug Doors / Emergency Jettisoning System - Inspection

Airbus Helicopters (Eurocopter) EC 225 Series Helicopters

2014-0263 - Doors - Cabin Sliding Plug Doors / Emergency Jettisoning System - Inspection

Robinson Helicopter Company R22 Series Helicopters

2014-23-16 - Main Rotor Blades - Skin Disbonding - Inspection

Robinson Helicopter Company R44 Series Helicopters

2014-23-16 - Main Rotor Blades - Skin Disbonding - Inspection

Below 5700 kgs

Piper PA-31 Series Aeroplanes

AD/PA-31/41 - Exhaust Tailpipe Support Bracket - Installation - CANCELLED

Above 5700 kgs

Airbus A319, A320 and A321 Series Aeroplanes

2014-0207 (Correction) - Oxygen - Chemical Emergency Oxygen Containers - Modification
2014-0237R1 - Navigation - Airspeed Pitot Probes - Replacement
2014-0256 - Equipment / Furnishings - Passenger Service Unit Jiffy Joint Connectors - Inspection
2014-0258 - Power Plant - Aft Engine Mount Bolts - Re-Torque
2014-0260 - Time Limits / Maintenance Checks - Airworthiness Limitations Section (ALS) Part 5 Fuel Airworthiness Limitations - Amendment
2014-0259 - Fuselage - External Fuselage Skin - Inspection
2014-0266-E - Airplane Flight Manual - Undue Activation of Alpha Protection - Emergency Procedure

Airbus A330 Series Aeroplanes

2014-0257 - Flight Controls - Trimmable Horizontal Stabilizer Actuator - Identification / Replacement
2014-0267-E - Airplane Flight Manual - Undue Activation of Alpha Protection - Emergency Procedure

Boeing 737 Series Aeroplanes

AD/B737/224 Amdt 4 - Horizontal Stabiliser Attachment Pins and Bolts - Inspection
2014-23-10 - Fuselage Frame - Cracking of Cutout in Web of BS Frame 303.9

Boeing 747 Series Aeroplanes

2014-23-11 - Upper Chords of the Upper Deck Floor Beams at Stations (STA) 340 through 520 - Inspection / Modification

Boeing 787 Series Aeroplanes

2014-23-12 - Crew Oxygen System Rework

2014-24-06 - Cabin Crew Seat Restraint System Fitting

Bombardier CL-600 Series Aeroplanes

CF-2014-42 - Landing Gear - Main Landing Gear Door Forward Member Cracking

CF-2014-44 - Flight Controls - Elevator Control System - Disconnect

Bombardier DHC-8 Series Aeroplanes

CF-2014-43 - Propeller Overspeed Governor - Incorporation of New Certification Maintenance Requirement (CMR) Task

Turbine Engines

CFM International Turbine Engines - CFM56 Series

2014-0261 - Engine Fuel & Control - Engine Electronic Control - Software Update

Pratt & Whitney Canada Turbine Engines – PW100 Series

CF-2014-41 - Engine Fuel and Control - Fuel Spray Nozzle - Fuel Leaks Resulting In Engine Fire