



CASA AD Biweekly 10/2015 – 14 May 2015

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 1 May 2015 and 14 May 2015.

Rotorcraft

AgustaWestland A109 Series Helicopters

2015-0069 (Correction) - Equipment / Furnishings - Hoist - Test / Replacement

AgustaWestland AB139 and AW139 Series Helicopters

2015-0069 (Correction) - Equipment / Furnishings - Hoist - Test / Replacement

Airbus Helicopters (Eurocopter) AS 332 Series Helicopters

2015-0069 (Correction) - Equipment / Furnishings - Hoist - Test / Replacement

2015-0075 - Equipment / Furnishings - Emergency Locator Transmitter - Identification / Replacement

Airbus Helicopters Deutschland (Eurocopter) MBB-BK 117 Series Helicopters

2015-0069 (Correction) - Equipment / Furnishings - Hoist - Test / Replacement

Airbus Helicopters Deutschland (Eurocopter) EC 135 Series Helicopters

2015-0069 (Correction) - Equipment / Furnishings - Hoist - Test / Replacement

Airbus Helicopters (Eurocopter) EC 225 Series Helicopters

2015-0069 (Correction) - Equipment / Furnishings - Hoist - Test / Replacement

2015-0075 - Equipment / Furnishings - Emergency Locator Transmitter - Identification / Replacement

Airbus Helicopters (Eurocopter) SA 360 and SA 365 Series Helicopters

2015-0068-E - Placards and Markings - Installation / Replacement

2015-0069 (Correction) - Equipment / Furnishings - Hoist - Test / Replacement

2015-0075 - Equipment / Furnishings - Emergency Locator Transmitter - Identification / Replacement

Bell Helicopter Textron 412 and Agusta AB412 Series Helicopters

2015-0072-E - Windows - Passenger Doors / Window Frames - Inspection

2015-0069 (Correction) - Equipment / Furnishings - Hoist - Test / Replacement

Below 5700 kgs

Piper PA-11 (Cub), J-2 & J-3 Series Aeroplanes

2015-08-04 - Wing Lift Struts - Corrosion Damage - Inspection

Piper PA-18 and 19 (Super Cub) Series Aeroplanes

2015-08-04 - Wing Lift Struts - Corrosion Damage - Inspection

Piper PA-20 (Pacer) Series Aeroplanes

2015-08-04 - Wing Lift Struts - Corrosion Damage - Inspection

Piper PA-22 (Tri-Pacer and Colt) Series Aeroplanes

2015-08-04 - Wing Lift Struts - Corrosion Damage - Inspection

Above 5700 kgs

Airbus A319, A320 and A321 Series Aeroplanes

2015-0080 - Flight Controls - Trimmable Horizontal Stabilizer Actuator - Identification / Replacement

2015-0083 - Time Limits / Maintenance Checks - ALS Part 2 - Damage Tolerant Airworthiness
Limitation Items - Implementation

2015-0084 - Fuselage - Rear Fuselage Frame 68 - Inspection / Repair

2015-0085 - Fuselage - Emergency Exit Cut-Out Area - Modification

Airbus A330 Series Aeroplanes

2015-0079 - Landing Gear - Main Landing Gear Side Stay Upper Cardan Pin - Inspection

2015-0082 - Power Plant - Aft and Forward Engine Mount Bolts - Torque Check / Replacement

Airbus A380 Series Aeroplanes

2015-0047 (Correction) - Airplane Flight Manual - Engine Interface Power Management Reset -
Amendment

2013-0108R2 - Wings - Wing Rib Feet - Modification

BAe Systems (Operations) BAe 146 and AVRO 146-RJ Series Aeroplanes

2015-0073 - Landing Gear - Main Landing Gear Hinged Fairing Attachment Brackets - Inspection

Boeing 737 Series Aeroplanes

2015-08-09 - Body Station 727 Bulkhead Lower Frame - Lower frame Web and Inner Chord Cracking -
Inspection

Boeing 747 Series Aeroplanes

2015-09-05 - Main Equipment Centre Drip Shield and Exhaust Plenum - Modification

Boeing 767 Series Aeroplanes

2015-09-09 - Outboard Flap - Aft Lower Lugs - Deflection Control Track - Inspection / Replacement

Boeing 787 Series Aeroplanes

2015-09-07 - Electrical Power - Generator Control Units (GCUs)

Bombardier CL-600 Series Aeroplanes

CF-2015-09 - Nacelle/Pylon - Non-conforming Bushing Holes on the Engine Mount Rib

Bombardier DHC-8 Series Aeroplanes

CF-2011-14R1 - Landing Gear - Main Landing Gear Retraction Actuator - Retract Port Flexible Hose
Failure

Dassault Aviation Falcon 7X Series Aeroplanes

2015-0076 - Electrical Power - Ram Air Turbine - Deployment / Placard Replacement

Fokker Services F28 Series Aeroplanes

2015-0077 - Landing Gear - Hydraulic Hose Restrictor Check Valve Screen - Inspection

2015-0078 - Airplane Flight Manual / Abnormal Procedures - Unpowered Aileron Actuator /
Maximum Speed Reduction - Implementation

Fokker Services F100 (F28 Mk 100) Series Aeroplanes

2015-0077 - Landing Gear - Hydraulic Hose Restrictor Check Valve Screen - Inspection

2015-0078 - Airplane Flight Manual / Abnormal Procedures - Unpowered Aileron Actuator /
Maximum Speed Reduction - Implementation

Turbine Engines

Turbomeca Turbine Engines - Arrius Series

2015-0049 (Correction) - Oil - Oil Pump Drive Link / Lubricating Device - Inspection