



## CASA AD Biweekly 13/2015 – 25 June 2015

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 12 June 2015 and 25 June 2015.

### **Rotorcraft**

#### **Airbus Helicopters (Eurocopter) AS 332 Series Helicopters**

2015-0112 - Ice and Rain Protection - Electrical Multi-Purpose Air Intakes - Modification

#### **Airbus Helicopters (Eurocopter) EC 225 Series Helicopters**

2015-0112 - Ice and Rain Protection - Electrical Multi-Purpose Air Intakes - Modification

#### **Bell Helicopter Textron Canada (BHTC) and Agusta Bell 206 Series Helicopters**

AD/BELL 206/114 - Fuel System Flow Switches - CANCELLED  
CF-2015-14 - Fuel System - Flow Switch

#### **Bell Helicopter Textron 412 and Agusta AB412 Series Helicopters**

2015-0106 - Equipment / Furnishings - External Cargo Hook Installation / Suspension Assembly Nuts - Inspection / Replacement

#### **Bell Helicopter Textron Canada (BHTC) 429 Series Helicopters**

CF-2015-15 - Time Limits & Maintenance Checks - Life-Limited Pylon Restraint Spring Assembly Rod End Not Serialized

### **Below 5700 kgs**

#### **Pilatus Aircraft PC-12 Series Aeroplanes**

2015-0111 - Flight Controls - Aileron Control System / Universal Joints - Replacement

### **Above 5700 kgs**

#### **Airbus A330 Series Aeroplanes**

2015-0101R1 - Fuselage - Skin and Structure / Allowable Damage Limits - Records Check / Repair

#### **Airbus A380 Series Aeroplanes**

2013-0108R3 - Wings - Wing Rib Feet - Modification  
2015-0114 - Time Limits / Maintenance Checks - Damage Tolerant Airworthiness Limitation Items - ALS Part 2 - Amendment

#### **Boeing 747 Series Aeroplanes**

2015-12-07 - Krueger (VCK) Flaps - Leading Edge - Delamination Damage - Inspection / Repair

## **Boeing 767 Series Aeroplanes**

2015-12-11 - Cargo Door Rotary Actuators - Inspection / Replacement

## **Boeing 777 Series Aeroplanes**

2015-12-11 - Cargo Door Rotary Actuators - Inspection / Replacement

2015-12-03 (Correction) - Rudder - Rudder Control Load Loop - Excessive Freeplay Detection - Inspection

## **Bombardier DHC-8 Series Aeroplanes**

CF-2015-13 - Stabilizers - Cracked Barrel Nut at the Horizontal Stabilizer to Vertical Stabilizer Attachment Joint

## **Fokker Services F28 Series Aeroplanes**

2015-0113 - Wings - Rear Spar Lower Girder - Inspection / Modification

## **Fokker Services F100 (F28 Mk 100) Series Aeroplanes**

2015-0113 - Wings - Rear Spar Lower Girder - Inspection / Modification

## **Learjet 45 Series Aeroplanes**

2015-12-06 - Windshield - Support (Coupe Rails) - Non-Conforming - Inspection

## **Turbine Engines**

### **Honeywell International Turbine Engines - TPE 331 Series**

2015-12-04 - Fuel Control Unit Drive Spline

### **Rolls Royce Turbine Engines - RB211 Series**

2015-0103 (Correction) - Rolls-Royce RB211-535E4 - Engine - Critical Parts - Identification / Replacement

### **Rolls Royce Turbine Engines - RB211 TRENT 700 Series**

2015-0105 - Engine - High / Intermediate Pressure Turbine Bearing Support Oil Feed Tube Sealing Sleeve - Inspection / Replacement

### **Rolls Royce Deutschland Turbine Engines - Tay Series**

2015-0050R1 - Engine - Stages 2 and 3 Low Pressure Turbine Discs - Inspection / Replacement

## **Equipment**

### **Electrical Equipment Miscellaneous (including Magnetos)**

AD/ELECT/11 Amdt 1 - Leach Relays - Control Terminal Insulation - CANCELLED

### **Radio Communication (including Emergency Transmitters and Navigation Equipment)**

2015-10-51 - Avidyne Integrated Flight Displays (IFDs) - Airplane Flight Manual (AFM) or Airplane Flight Manual Supplement (AFMS) Limitation