



CASA AD Biweekly 2/2015 – 22 January 2015

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 9 January 2015 and 22 January 2015.

Rotorcraft

Aircraft - General

AD/GENERAL/87 - Primary Flight Control Cable Assembly Retirement

Airbus Helicopters (Eurocopter) AS 332 Series Helicopters

2014-0263R1 - Doors - Cabin Sliding Plug Doors / Emergency Jettisoning System - Inspection

Airbus Helicopters (Eurocopter) EC 225 Series Helicopters

2014-0263R1 - Doors - Cabin Sliding Plug Doors / Emergency Jettisoning System - Inspection

Bell Helicopter Textron Canada (BHTC) 206A-1 (OH-58A) Series Helicopters

PAD/OH-58/8 Amdt 1 - Main Rotor Mast Cracking

Kawasaki BK 117 Series Helicopters

TCD-8201B-2015 - Goodrich Rescue Hoist

Below 5700 kgs

Aircraft - General

AD/GENERAL/87 - Primary Flight Control Cable Assembly Retirement

Britten-Norman Aircraft BN2 Series Aeroplanes

AD/BN-2/84 Amdt 2 - Pitot/Static Pressure Head - CANCELLED
2006-0143R1 - Navigation - Pitot / Static Pressure Head - Inspection / Test

Grob-Werke G115 Series Aeroplanes

2015-0010 - Starting - Starter Solenoid - Inspection / Modification

Socata (Aerospatiale) TBM700 Series Aeroplanes

AD/TBM 700/46 - Main Landing Gear Shock Strut Cylinder - CANCELLED
2006-0085R2 - Landing Gear - Main Landing Gear Shock Strut Cylinder - Inspection / Replacement / Modification

Above 5700 kgs

Aircraft - General

AD/GENERAL/87 - Primary Flight Control Cable Assembly Retirement

Airbus A319, A320 and A321 Series Aeroplanes

2014-0275R1 - Oxygen - Passenger Chemical Oxygen Generators - Replacement
2015-0001R1 - Doors - Main Landing Gear Fixed Fairing Assembly - Inspection
2015-0004 - Power Plant - Forward Engine Mount Pin - Identification / Replacement

Airbus A330 Series Aeroplanes

2015-0008 - Hydraulic Power - Ram Air Turbine Actuator - Identification / Modification
2015-0009 - Hydraulic Power - High Pressure Manifold Check Valves - Inspection / Modification

Airbus A380 Series Aeroplanes

2014-0016R1 (Correction) - Wing Inboard Leading Edge Droop Nose Gooseneck Inspection/ Repair/ Replace
2015-0002 - Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 4 - System Equipment Maintenance Requirements - Implementation
2015-0003 - Fuselage - Cone / Rear Fuselage / Section 19 - Modification

Dassault Aviation Mystere-Falcon 20 and 200 Series Aeroplanes

2015-0007 - Doors - Crew / Passenger Door - Inspection / Adjustment / Operational Test

Dassault Aviation Falcon 50 and 900 Series Aeroplanes

2015-0005 - Airplane Flight Manual - Yaw Damper Operational Procedure - Amendment
2015-0006 - Lightning - Anti-Collision Light Bonding - Modification
2015-0007 - Doors - Crew / Passenger Door - Inspection / Adjustment / Operational Test

Dassault Aviation Falcon 2000 Series Aeroplanes

2015-0005 - Airplane Flight Manual - Yaw Damper Operational Procedure - Amendment
2015-0006 - Lightning - Anti-Collision Light Bonding - Modification

Turbine Engines

Pratt and Whitney Canada Turbine Engines - PT6B Series

CF-2015-01 - Engine Indicating - Incorrect Engine Torque Indication