



CASA AD Biweekly 16/2015 – 6 August 2015

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 24 July 2015 and 6 August 2015.

Rotorcraft

AgustaWestland A109 Series Helicopters

2015-0160 - Equipment / Furnishings - Hoist - Test / Replacement

AgustaWestland AB139 and AW139 Series Helicopters

2015-0155 - Ice and Rain Protection - Full Ice Protection System Tail Rotor Slip Ring - Inspection / Replacement

2015-0160 - Equipment / Furnishings - Hoist - Test / Replacement

Airbus Helicopters (Eurocopter) AS 332 Series Helicopters

2015-0149 - Windows - Cabin Windows / Jettisoning System - Inspection

2015-0153-E - Tail Rotor - Rotor Blades - Inspection

2015-0156 (Correction) - Doors - Cabin Sliding Plug Doors / Emergency Jettisoning System - Inspection

2015-0160 - Equipment / Furnishings - Hoist - Test / Replacement

Airbus Helicopters Deutschland (Eurocopter) MBB-BK 117 Series Helicopters

2015-0160 - Equipment / Furnishings - Hoist - Test / Replacement

Airbus Helicopters Deutschland (Eurocopter) EC 135 Series Helicopters

2015-0160 - Equipment / Furnishings - Hoist - Test / Replacement

Airbus Helicopters (Eurocopter) EC 225 Series Helicopters

2015-0149 - Windows - Cabin Windows / Jettisoning System - Inspection

2011-0136R2 - Equipment and Furnishings - VHF Antenna for Emergency Flotation Gear Protection - Installation

2015-0156 (Correction) - Doors - Cabin Sliding Plug Doors / Emergency Jettisoning System - Inspection

2015-0160 - Equipment / Furnishings - Hoist - Test / Replacement

Airbus Helicopters (Eurocopter) SA 360 and SA 365 Series Helicopters

2015-0160 - Equipment / Furnishings - Hoist - Test / Replacement

Bell Helicopter Textron 204 Series Helicopters

2015-15-04 - Main Rotor Blade Grips - Removal From Service

Bell Helicopter Textron 205 Series Helicopters

2015-15-04 - Main Rotor Blade Grips - Removal From Service

Bell Helicopter Textron 212 Series Helicopters

2015-15-04 - Main Rotor Blade Grips - Removal From Service

Bell Helicopter Textron 412 and Agusta AB412 Series Helicopters

2015-0160 - Equipment / Furnishings - Hoist - Test / Replacement (Mandatory for AgustaWestland AB412 only)

Below 5700 kgs

Pacific Aerospace 750XL Series Aeroplanes

DCA/750XL/18A - Fin Forward Pickup - Inspection

Reims Aviation F406 Series Aeroplanes

2015-0159-E - Flight Controls - Rudder Control Pedal Torque Tubes - Inspection / Replacement

Robin Aviation Series Aeroplanes (includes Alpha Aviation R2000 Series)

2015-0154 - Air - Carburettor Heated Air Intake Box - Modification

Above 5700 kgs

Airbus A380 Series Aeroplanes

2015-0151 - Time Limits / Maintenance Checks - Damage Tolerant Airworthiness Limitation Items - ALS Part 2 - Amendment

Boeing 737 Series Aeroplanes

2015-15-05 - Forward Service Door Cracking

Boeing 747 Series Aeroplanes

2015-15-01 - Upper and Lower skins Fuselage lap joints
2015-13-06 - Outboard Flange of the Longerons Extension Fitting
2015-15-11 - Fuselage Skin at Certain Lower Circumferential Splices

Boeing 777 Series Aeroplanes

2015-15-15 - Wing Skin Panel Gaps - Inspection

Bombardier CL-600 Series Aeroplanes

CF-2014-20R1 - Power Plant - Engine Fan Cowl Panel Dislodgement During Flight

Turbine Engines

Pratt and Whitney Canada Turbine Engines - PT6A Series

CF-2015-23 - Fuel Control - Fuel Control Unit Bellow Leak

Rolls Royce Turbine Engines - RB211 Series

2015-0148 (Correction) - Engine - Critical Parts - Identification / Replacement

Turbomeca Turbine Engines - Arriel Series

2015-0064R1 - Engine - Front Support Pins - Inspection / Replacement

Equipment

Propellers - Variable Pitch - Dowty Rotol

2015-0158 - Propellers - Rear Half Hub Dowel Holes - Inspection / Replacement