



## CASA AD Biweekly 4/2015 – 19 February 2015

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 6 February 2015 and 19 February 2015.

### **Rotorcraft**

#### **AgustaWestland A109 Series Helicopters**

2015-0022 - Time Limits / Maintenance Checks - Airworthiness Limitations - Implementation  
2015-0025-E - Rotor(s) - Main Rotor Blades - Identification / Replacement

#### **Airbus Helicopters (Eurocopter) AS 350 and EC 130 Series Helicopters**

2015-0020 - Doors - Sliding Door Star Support - Modification

#### **Airbus Helicopters Deutschland (Eurocopter) MBB-BK 117 Series Helicopters**

2015-0019R1 - Optional Equipment - External Rescue Hoist System - Inspection / Modification

#### **Airbus Helicopters Deutschland (Eurocopter) BO105 Series Helicopters**

2015-0017 - Equipment / Furnishings - Rescue Hoist Control Grip - Inspection / Replacement

#### **Airbus Helicopters (Eurocopter) EC 120 Series Helicopters**

2015-0020 - Doors - Sliding Door Star Support - Modification

#### **Enstrom Helicopter Corporation F-28 Series Helicopters**

2015-04-51 - Main Rotor Blade Spindle - Inspection / Replacement

#### **Kawasaki BK 117 Series Helicopters**

TCD-8379A-2015 - Optional Equipment - External Rescue Hoist System - Deactivation

#### **Sikorsky Aircraft Corporation S-92 Series Helicopters**

2014-12-11R1 - Rotorcraft Flight Manual (RFM) Revision

### **Below 5700 kgs**

#### **Grob-Werke G115 Series Aeroplanes**

2015-0010R1 - Starting - Starter Solenoid - Inspection / Modification

#### **Quest Aircraft Design Kodiak Series Aeroplanes**

2015-02-15 - Cracks in Lower Elevator Skins

### **Above 5700 kgs**

#### **Airbus A319, A320 and A321 Series Aeroplanes**

2015-0021 - Powerplant - Aft Engine Mount Retainers - Inspection / Replacement

### **Airbus A380 Series Aeroplanes**

2012-0052R1 - Wings - Leading Edge Shear Cleats - Inspection / Replacement

### **ATR-GIE Avions de Transport Regional ATR 42 Series Aeroplanes**

2015-0018 - Equipment / Furnishing - Type III Emergency Exit Door - Modification

### **ATR-GIE Avions de Transport Regional ATR 72 Series Aeroplanes**

2015-0018 - Equipment / Furnishing - Type III Emergency Exit Door - Modification

### **Boeing 737 Series Aeroplanes**

2015-02-26 - Body Station (BS) 520 Seat Track Link Assembly

### **Boeing 747 Series Aeroplanes**

2015-03-04 - Main Entry Door 1 Cut Out - Lower Forward Corner Skin Cracking - Inspection / Repair

### **Embraer ERJ 190 Series Aeroplanes**

2015-02-01 - Replacement of the Low-stage Bleed Check Valve and the Controller Operational Program of the Air Management System (AMS)

## **Piston Engines**

### **Lycoming Piston Engines**

2015-02-07 - Propeller Governor Shaft - Set Screw Rework

## **Turbine Engines**

### **Rolls Royce (Allison) Turbine Engines - AE 3007 Series**

2015-02-08 - Reduction of the Approved Life Limits of Turbine Wheels