



Australian Government
Civil Aviation Safety Authority

CASA AD Biweekly 18/2015 – 3 September 2015

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 21 August 2015 and 3 September 2015.

Rotorcraft

AgustaWestland AB139 and AW139 Series Helicopters

2015-0172 - Landing Gear - Emergency Flotation System Control Panel - Replacement

Airbus Helicopters (Eurocopter) AS 350 and EC 130 Series Helicopters

2015-0178 - Rotorcraft Flight Manual - Chapter Normal Procedures - Engine Prestart Check / Run-up Check / Engine and Rotor Shutdown - Amendment

Airbus Helicopters (Eurocopter) AS 355 Series Helicopters

2015-0181 - Fire Protection - Engine Fire Extinguisher System - Modification

Below 5700 kgs

ASI Aviation (Reims) F406 Series Aeroplanes

2015-0159R1 - Flight Controls - Rudder Control Pedal Torque Tubes - Inspection / Replacement

Avtech (Jabiru Aircraft) Series Aeroplanes

PAD/JABIRU/2 - Wing Attachment Bolts - Life Limit

Britten-Norman Aircraft BN2 Series Aeroplanes

2015-0184 - Engine Controls - Engine Control Cables - Inspection / Replacement

Cessna 500 (Citation) Series Aeroplanes

2015-17-12 - Air Conditioning System Motor

Pacific Aerospace (Airparts) FU24 Series Aeroplanes

DCA/FU24/178B - Vertical Stabiliser - Replacement

Above 5700 kgs

Airbus A330 Series Aeroplanes

2015-0183 - Equipment / Furnishings - Passenger / Crew and Emergency Exit Door Slide and Slide Raft Attachments - Inspection

2014-0120R1 - Landing Gear - Main Landing Gear Bogie Beam - Inspection / Repair

ATR-GIE Avions de Transport Regional ATR 42 Series Aeroplanes

2015-0171 - Electrical Routing - Electronic Rack 90 VU Shelf / Electrical Harness - Inspection

ATR-GIE Avions de Transport Regional ATR 72 Series Aeroplanes

2015-0171 - Electrical Routing - Electronic Rack 90 VU Shelf / Electrical Harness - Inspection

BAe Systems (Operations) BAe 146 and AVRO 146-RJ Series Aeroplanes

2015-0180 - Air Conditioning - Fuselage Skin Discharge Valves - Inspection / Repair

Bombardier BD-700 Series Aeroplanes

CF-2015-25 - Oxygen - Oxygen System Flexible Hose - Incorrect Burst Pressure

Boeing 737 Series Aeroplanes

2015-16-08 - Fuselage Lap Splice Lower Skin Lower Fastener Holes - Inspection

Bombardier CL-600 Series Aeroplanes

CF-2015-26 - Fuel - Chaffing of the Auxiliary Power Unit Negative-G Fuel Feed Drain Line

CF-2015-27 - Hydraulic Power - No. 3 Hydraulic System Reservoir Leak

Cessna 550 (Citation II) Series Aeroplanes

2015-17-12 - Air Conditioning System Motor

Cessna 560 (Citation V) Series Aeroplanes

2015-17-12 - Air Conditioning System Motor

Cessna 650 (Citation III) Series Aeroplanes

2015-17-12 - Air Conditioning System Motor

Turbine Engines

Rolls Royce Turbine Engines - RB211 TRENT 900 Series

2012-0220R2 - Engine - Low Pressure Turbine Disc Seal Fins and Interstage Seals - Inspection / Replacement

Turbomeca Turbine Engines - Arriel Series

2015-0175 - Engine Indicating - Tachometer Boxes - Replacement

2015-0177 - Engine - Torque Conformation Box - Check