



CASA AD Biweekly 24/2015 – 26 November 2015

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 13 November 2015 and 26 November 2015.

Rotorcraft

AgustaWestland A109 Series Helicopters

2015-0226R1 - Equipment / Furnishings - Hoist - Test / Replacement
2015-0227 - Rotorcraft Flight Manual - Limitations Section - Amendment

AgustaWestland AB139 and AW139 Series Helicopters

2015-0226R1 - Equipment / Furnishings - Hoist - Test / Replacement

Airbus Helicopters (Eurocopter) AS 332 Series Helicopters

2015-0226R1 - Equipment / Furnishings - Hoist - Test / Replacement

Airbus Helicopters Deutschland (Eurocopter) MBB-BK 117 Series Helicopters

2015-0226R1 - Equipment / Furnishings - Hoist - Test / Replacement

Airbus Helicopters Deutschland (Eurocopter) EC 135 Series Helicopters

2015-0226R1 - Equipment / Furnishings - Hoist - Test / Replacement

Airbus Helicopters (Eurocopter) EC 225 Series Helicopters

2015-0226R1 - Equipment / Furnishings - Hoist - Test / Replacement

Airbus Helicopters (Eurocopter) SA 360 and SA 365 Series Helicopters

2015-0226R1 - Equipment / Furnishings - Hoist - Test / Replacement

Bell Helicopter Textron 412 and Agusta AB412 Series Helicopters

2015-0226R1 - Equipment / Furnishings - Hoist - Test / Replacement

Above 5700 kgs

Airbus A330 Series Aeroplanes

2015-0224 - Fuel - Fuel Tanks Safety - Inspection / Modification

Airbus A380 Series Aeroplanes

2015-0188R1 - Air Conditioning - Electronic Centralized Aircraft Monitoring / Flight Warning System - Software Update / Aircraft Flight Manual Changes

BAe Systems (Operations) BAe 146 and AVRO 146-RJ Series Aeroplanes

2015-0228 - Fuselage - Frame 29 Wing-to-Fuselage Lug Plate Attachment Joint - Inspection

Boeing 737 Series Aeroplanes

AD/B737/87 Amdt 2 - Fuselage Lap Joints, Lower Skins - CANCELLED
2015-21-06 - Fuselage Lap Joints

Boeing 747 Series Aeroplanes

2015-23-10 - Outboard Stowage Bin Modules
2015-23-11 - Fuselage Skin Lap Joint Fatigue Cracking

Turbine Engines

General Electric Turbine Engines - GEnx Series

2015-23-04 - Oil Filler Cap - Ball Valve Replacement