



Australian Government
Civil Aviation Safety Authority

CASA AD Biweekly 23/2016 – 10 November 2016

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 28 October and 10 November 2016.

Rotorcraft

Airbus Helicopters (Eurocopter) AS 350 and EC 130 Series Helicopters

2016-0220 - Rotor Flight Controls - Dual Hydraulic System - Modification

Airbus Helicopters (Eurocopter) AS 355 Series Helicopters

2016-0109R1 - Fuel - FUELTRON Flowmeter - Removal

Bell Helicopter Textron 204 Series Helicopters

AD/BELL 204/19 Amdt 3 - Main Rotor Blade Cracking and Corrosion - CANCELLED

Above 5700 kgs

Airbus A319, A320 and A321 Series Aeroplanes

2016-0222 - Wings - Bottom Panel 2 at Rib 2 Interface - Inspection

BAe Systems (Operations) BAe 146 and AVRO 146-RJ Series Aeroplanes

2016-0225 - Wings - Rear Spar Root Joint Attachment Fittings at Wing Rib 2 - Inspection

BAe Systems (Operations) Jetstream 3100 and 3200 Series Aeroplanes

2016-0224 - Landing Gear - Main Landing Gear - Inspection / Replacement

Boeing 737 Series Aeroplanes

2016-22-14 - Chafing of Wire Bundles in the Right Side of the MLG Wheel Well

Boeing 757 Series Aeroplanes

2016-22-09 - Section 43 and Section 46 - Structure - Inspection for Incorrectly Installed Rivets on Fuselage Skin Lap Splices

Bombardier CL-600 Series Aeroplanes

AD/CL-600/71 Amdt 3 - State of Design Airworthiness Directives

CF-2011-30R1 - Fuselage - Cracking on the Forward Face of the Rear Pressure Bulkhead Web