



CASA AD Biweekly 2/2016 – 21 January 2016

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 7 January and 21 January 2016.

Rotorcraft

Airbus Helicopters (Eurocopter) AS 332 Series Helicopters

2016-0019 - Equipment / Furnishings - Life Raft / Banjo Bolt - Inspection

Airbus Helicopters (Eurocopter) AS 350 and EC 130 Series Helicopters

2014-0229R1 - Oil - Main Gearbox Oil Cooler Fan Hopper - Inspection

Airbus Helicopters (Eurocopter) EC 225 Series Helicopters

2016-0019 - Equipment / Furnishings - Life Raft / Banjo Bolt - Inspection

Below 5700 kgs

Piper PA-46 (Malibu) Series Aeroplanes

2016-01-01 - Wing Upper Skin Joints - Inspection

Above 5700 kgs

Airbus A319, A320 and A321 Series Aeroplanes

2016-0010 - Powerplant - Aft Engine Mount Retainers - Inspection / Replacement

2016-0015 - Fuselage - Door Stop Fitting Holes - Inspection / Repair

2016-0018 - Landing Gear - Main Landing Gear Side Stay Assemblies - Replacement / Modification

Airbus A330 Series Aeroplanes

2015-0119 (Correction) - Oxygen - Chemical Oxygen Generators - Replacement

2016-0011 - Time Limits / Maintenance Checks - System Equipment Maintenance Requirements / ALS
Part 4 - Amendment

Airbus A380 Series Aeroplanes

2016-0007 - Fuselage - Cabin and Cargo Compartment Structural Parts - Inspection / Replacement
[Improper Heat Treatment]

Boeing 737 Series Aeroplanes

2016-01-05 - Incorrectly Identified Fire Extinguisher Bottle Squib and Pressure Switches

Boeing 747 Series Aeroplanes

AD/B747/321 - Body Station 2231 Frame Inner Chord - CANCELLED

2015-25-03 (Correction) - Outboard Flap Actuator

2016-01-04 - Body Station 2231 Frame Inner Chord

Bombardier CL-600 Series Aeroplanes

CF-2016-03 - Flight Controls - Flap and Slat Torque Tube Corrosion

Bombardier DHC-8 Series Aeroplanes

CF-2016-04 - Ice and Rain Protection - Pitot and Static System - Pitot Probe Heater Circuit Breaker Tripping During Adverse Environmental Conditions

Turbine Engines

General Electric Turbine Engines - GE90 Series

2015-27-01 - Uncontained Failure of the HPC Stage 8-10 Spool

Turbomeca Turbine Engines - Arriel Series

2016-0009 - Engine - Gas Generator (Module 03) / Piston Shaft Small Diameter Labyrinth - Modification / Replacement

Turbomeca Turbine Engines - Makila Series

2016-0016 - Engine - Power Turbine Module 04 Bearing Supply Swivel Union - Check of Tightening Torque