



CASA AD Biweekly 11/2017 – 1 June 2017

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 19 May and 1 June 2017.

Rotorcraft

Aircraft - General

PAD/GENERAL/87 Amdt 1 - Primary Flight Control Cable Terminals - Detailed Visual Inspections

Airbus Helicopters (Eurocopter) AS 350 and EC 130 Series Helicopters

2017-0089 - Main Rotor - MR Mast Upper Bearing Lubrication / MR Mast Jet Oil Hose - Inspection

Airbus Helicopters (Eurocopter) AS 355 Series Helicopters

2017-0089 - Main Rotor - MR Mast Upper Bearing Lubrication / MR Mast Jet Oil Hose - Inspection

Airbus Helicopters Deutschland (Eurocopter) MBB-BK 117 Series Helicopters

2017-0094 - Rotors Flight Control - Trim Actuators - Replacement

Bell Helicopter Textron Canada (BHTC) 429 Series Helicopters

CF-2017-16 - Time Limits & Maintenance Checks - New Airworthiness Life Limitations and Certification Maintenance Requirements

Below 5700 kgs

Aircraft - General

PAD/GENERAL/87 Amdt 1 - Primary Flight Control Cable Terminals - Detailed Visual Inspections

Cessna 400 Series Aeroplanes

2017-10-09 - Nacelle Fittings - Inspection / Replacement

Diamond Aircraft Industries DA 42 Series Aeroplanes

2017-0090 - Engine Exhaust - Exhaust Pipes - Modification / Inspection

Piper PA-31 Series Aeroplanes

2017-10-20 - Fuselage Station (FS) 332.00 Bulkhead Assembly - Inspection

Viking Air DHC-2 (Beaver) Series Aeroplanes

CF-2017-17 - Wing - Cracking of Flap and Aileron hinge arm support brackets and Rear Spar Web

Above 5700 kgs

Aircraft - General

PAD/GENERAL/87 Amdt 1 - Primary Flight Control Cable Terminals - Detailed Visual Inspections

Airbus A319, A320 and A321 Series Aeroplanes

AD/A320/77 Amdt 1 - Loral DFDR F800 Damping Rack Installation
AD/A320/82 Amdt 1 - Wing Rear Spar Pressurised Floor Pick-Up Angles
AD/A320/85 Amdt 1 - Probe Heat Computer
AD/A320/123 Amdt 1 - Ram Air Turbine Actuator
2017-0091R1 - Navigation - Traffic Collision Avoidance System Processor - Modification (Software Update) / Replacement

Airbus A330 Series Aeroplanes

2017-0091R1 - Navigation - Traffic Collision Avoidance System Processor - Modification (Software Update) / Replacement

Boeing 737 Series Aeroplanes

2017-10-22 - Aft Pressure Bulkhead Web Lap Splices - Inspection
2017-11-01 - Horizontal Stabilizer - Joint Inspection
2017-10-21 - Lap Joint Skin - Modification
2017-10-07 - Fuselage - Aft Skin - Inspection, Repair and Skin Panel Replacement
2017-10-08 - Fuselage - Aft Skin - Inspection, Repair and Skin Panel Replacement

Boeing 747 Series Aeroplanes

2017-09-10 - Wing Spars - Front Spar Web - Inspection

Boeing 787 Series Aeroplanes

2017-09-08 - Variable Frequency Starter Generator (VFSG) Power Feeder Cable terminal Lugs - Inspection
2017-10-16 - Sealant above the Engine Pylon between the Wing Skin and the Vapor Barrier - Inspection

Bombardier DHC-8 Series Aeroplanes

CF-2017-04R1 - Fuel System - Corrosion and Wear of Hydraflow Couplings and Sleeves, Fuel Tube End Ferrules, and Fuel Component End Ferrules
CF-2017-18 - Windows - Windshield Cracking

Fokker Services F28 Series Aeroplanes

2017-0095 - Time Limits / Maintenance Checks - ALS Part 2 - Airworthiness Limitation Items and Safe Life Items - Implementation

Fokker Services F100 (F28 Mk 100) Series Aeroplanes

2017-0095 - Time Limits / Maintenance Checks - ALS Part 2 - Airworthiness Limitation Items and Safe Life Items - Implementation

Learjet 60 Series Aeroplanes

2017-11-09 - Fuselage Skin Between Stringers (S)-2L and S-2R - Inspection

Equipment

Propellers - Fixed Pitch

2017-0092-E - Societe Duc H-FLR2 (FLAIR-2) Propellers - Removal from Service

Seats and Berths

2017-09-09 - Zodiac Seating Systems - Removal from Service