



## CASA AD Biweekly 26/2018 – 27 December 2018

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 14 December and 27 December 2018.

### **Rotorcraft**

#### **Airbus Helicopters (Eurocopter) AS 332 Series Helicopters**

2018-0282 - Fuselage - Main Gearbox Suspension Bar Rear Attachment Fitting Screws - Inspection

#### **Airbus Helicopters (Eurocopter) AS 350 and EC 130 Series Helicopters**

2018-0287 - Rotors Flight Control - Tail Rotor Gearbox Actuating Rod - Inspection

2018-25-17 - Air Comm Air Conditioning Systems Electrical Connectors - Replacement (Moved from EQUIPMENT AD Section)

#### **Airbus Helicopters (Eurocopter) AS 355 Series Helicopters**

2018-0287 - Rotors Flight Control - Tail Rotor Gearbox Actuating Rod - Inspection

#### **Airbus Helicopters Deutschland (Eurocopter) MBB-BK 117 Series Helicopters**

2018-0283 - Rotors Flight Control - Main Rotor Actuator - Inspection

#### **Airbus Helicopters Deutschland (Eurocopter) EC 135 Series Helicopters**

2018-0284 - Rotors Flight Control - Main Rotor Actuator - Inspection

#### **Bell Helicopter Textron Canada (BHTC) and Leonardo Helicopters (Agusta) AB206 Series Helicopters**

2018-25-17 - Air Comm Air Conditioning Systems Electrical Connectors - Replacement (Moved from EQUIPMENT AD Section)

#### **Bell Helicopter Textron Canada (BHTC) 407 Series Helicopters**

2018-25-17 - Air Comm Air Conditioning Systems Electrical Connectors - Replacement (Moved from EQUIPMENT AD Section)

#### **Bell Helicopter Textron Canada (BHTC) 429 Series Helicopters**

CF-2018-35 - Tail Rotor Drive - Tail Rotor Gearbox - Introduction of Attachment Hardware Recurring Torque Check

#### **Leonardo Helicopters (AgustaWestland) A109 Series Helicopters**

2018-0280 - Rotors Flight Control - Mixing Control System Rigid Connecting Link - Inspection

#### **Leonardo Helicopters (AgustaWestland) A119 Series Helicopters**

2018-0280 - Rotors Flight Control - Mixing Control System Rigid Connecting Link - Inspection

## **Leonardo Helicopters (AgustaWestland) AW189 Series Helicopters**

2018-0279 - Emergency Flotation System Inflation Hose - Inspection

## **Below 5700 kgs**

### **Pacific Aerospace 750XL Series Aeroplanes**

DCA/750XL/33 - Aileron Pivot Fork Assembly - Inspection

DCA/750XL/32A - NLG and MLG Attachment Bolts - Inspection

## **Above 5700 kgs**

### **Airbus A319, A320 and A321 Series Aeroplanes**

2018-0288 - Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 - Damage Tolerant Airworthiness Limitation Items - Implementation

2018-0289 - Fuselage - Service Door Stop Fitting Hole - Inspection / Repair

### **Airbus A330 Series Aeroplanes**

2018-0276 - Fuselage - Structural Parts / Joints - Modification / Reinforcement

### **Airbus A380 Series Aeroplanes**

2018-0275 - Wings - Frame 56 Vertical Cruciform Fittings - Inspection / Modification

### **Boeing 727 Series Aeroplanes**

2018-25-15 - Outboard Flap Track - Inspection

### **Boeing 777 Series Aeroplanes**

2018-25-11 - Electronic Engine Control (EEC) Wire Bundles and Clips - Inspection

### **Bombardier DHC-8 Series Aeroplanes**

CF-2018-34 - Flight Controls - Elevator Power Control Unit Bracket Cracking

### **Dassault Aviation Falcon 7X Series Aeroplanes**

2018-0277 - Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment Turbine Engines

### **Rolls Royce Turbine Engines - RB211 TRENT 700 Series**

2018-0291 - Engine - High Pressure Turbine Blades - Replacement

### **Safran Helicopter Engines (Turbomeca) Turbine Engines - Arriel Series**

2018-0273 - Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment

## **Equipment**

### **Airconditioning Equipment**

2018-25-17 - Air Comm Air Conditioning Systems Electrical Connectors - Replacement (Moved to ROTORCRAFT AD Section)