



## CASA AD Biweekly 4/2018 – 22 February 2018

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 9 February and 22 February 2018.

### **Rotorcraft**

#### **Airbus Helicopters (Eurocopter) AS 332 Series Helicopters**

2018-0039 - Windows - Jettisoning System - Installation  
2018-0042 - Tail Rotor Hub Assembly - Inspection

#### **Airbus Helicopters Deutschland (Eurocopter) MBB-BK 117 Series Helicopters**

2018-0046 - Tail Rotor Drive - Tail Gear Box - Inspection / Replacement

#### **Airbus Helicopters (Eurocopter) EC 225 Series Helicopters**

2018-0039 - Windows - Jettisoning System - Installation

### **Below 5700 kgs**

#### **CEAPR and Alpha Aviation (Avions Pierre Robin) Robin Series Aeroplanes**

AD/ROBIN/24 - Empennage Attach Bolts - CANCELLED

#### **Textron Aviation (Cessna) 400 Series Aeroplanes**

2018-03-03 - Left and Right Forward Lower Carry Through Spar Caps - Inspection

### **Above 5700 kgs**

#### **Airbus A319, A320 and A321 Series Aeroplanes**

2018-0038 - Fire Protection - Cargo Fire Extinguishing Bottles - Inspection  
2018-0041-E - Engine - Operational Restrictions

#### **Airbus A380 Series Aeroplanes**

2018-0043 - Power Plant - Rear Engine Mount Assembly - Inspection

#### **Boeing 717 Series Aeroplanes**

2018-03-04 - Rosemount Aerospace Model 851AK Pitot Probes repaired by CSI Aerospace Inc - Incorrect Airspeed Indication

#### **Boeing 757 Series Aeroplanes**

2018-03-10 - Fuselage Skin - Scribe Line Damage

#### **Boeing 777 Series Aeroplanes**

2018-02-20 - Aft Fuselage Corrosion

**Bombardier CL-600 Series Aeroplanes**

CF-2018-06 - Floodlight Panel - Cockpit Floodlight Water Penetration

CF-2014-44R2 - Flight Controls - Elevator Control System - Disconnect

**Turbine Engines****General Electric Turbine Engines - CT7 Series**

2018-03-13 - Main Propeller Shaft - Inspection

**Safran Helicopter Engines (Turbomeca) Turbine Engines - Arrius Series**

2018-0044 - Engine - Gas Generator (Module 02) / Power Turbine Wheel - Replacement

**Equipment****Flight and Engine Instruments (including Autopilots)**

2018-03-04 - Rosemount Aerospace Model 851AK Pitot Probes repaired by CSI Aerospace Inc -  
Incorrect Airspeed Indication