



CASA AD Biweekly 21/2018 – 18 October 2018

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 5 October and 18 October 2018.

Below 5700 kgs

Diamond Aircraft Industries DA 42 and DA 62 Series Aeroplanes

2018-0214 - Flight Controls - Rudder Pedal Gust Lock Mounts - Removal

GippsAero GA8 Series Aeroplanes

AD/GA8/10 - Airworthiness Limitations Section - Service Manual Chapter 4 - Amendment

Viking Air DHC-6 (Twin Otter) Series Aeroplanes

CF-2018-28 - Flight Controls - Worn Elevator Cables

Above 5700 kgs

Airbus A319, A320 and A321 Series Aeroplanes

AD/A320/204 Amdt 1 - Centre and Outer Wing Box at level of Rib 1 Junction - CANCELLED

2018-0218 - Wings - Center and Outer Wing Box at Level of Rib 1 Junction - Inspection

Airbus A380 Series Aeroplanes

2018-0215 - Aircraft Flight Manual - Fuel Quantity Indication System Procedure - Amendment

2018-0221 - Wings - Aileron Actuator Fittings - Inspection

Boeing 737 Series Aeroplanes

2018-20-13 (Correction) - Fuel Shutoff Valves - Motor-Operated Valves - Replacement

2018-20-24 - Airworthiness Limitations - Centre Fuel Tank

2018-21-08 - Body Station (STA) 259.5 Bulkhead Frame Web - Inspection

Boeing 757 Series Aeroplanes

2018-20-13 (Correction) - Fuel Shutoff Valves - Motor-Operated Valves - Replacement

Boeing 767 Series Aeroplanes

2018-20-13 (Correction) - Fuel Shutoff Valves - Motor-Operated Valves - Replacement

Boeing 787 Series Aeroplanes

2018-20-15 - Electrical Power - Generator Control Units (GCUs)

Bombardier CL-600 Series Aeroplanes

CF-2018-26 - Landing Gear - Main Landing Gear Side Stay Actuators Contain Non-Conforming Split Ball Bearing

Dassault Aviation Mystere-Falcon 20 and 200 Series Aeroplanes

2009-0175R1 - Engine - First Stage Low Pressure Turbine (LPT1) Blades / Vibration Monitoring
2012-0190 - Fire Protection - Extinguishing System - Defective Cartridges - Inspection / Replacement
2012-0189 - Fire Protection - Extinguishing System - Defective Charge Indicators - Inspection / Replacement
2008-0221 (Correction) - Maintenance Programme and Airworthiness Limitations Section of the Instructions for Continued Airworthiness - Revision
2008-0123 - Ice and Rain Protection - Anti-Ice Pipe Seal - Inspection / Replacement
2008-0072 - Air Conditioning - Pressurization Control Regulating Valve - Check
2007-0262 - Fuselage Structure - Cockpit Windows Frames - Modification
2007-0227 - Ice & Rain Protection - Collapsed Wing Anti-Ice Hoses - Replacement
2006-0185 - Flight Controls - Elevator Bellcrank - Inspection / Modification
2006-0156 - Doors - Over Wing Emergency Exit - Inspection
F-2003-419(B) - Fire Protection - Extinguishing Pipe in the Engine Area
2001-600-028(B) - Aircraft Structure - Windows Frames
1990-090-019(B)R2 - Major Corrosion Inspection
1999-450(B)R1 - Consequences of YK2 on Airborne Systems
1999-467-026(B) - Speed Limitations Associated with Arthur Q Unit Failure
98-114-023(B)R1 - Fire Extinguishing
96-246-022(B) - Wing to Fuselage Upper Fairings
96-092-021(B)R1 - Wing to Fuselage Upper Fairings
96-078-021(B) - Replacement of Polyurethane Foams in Fuselage Tanks
90-089-020(B)R1 - Supplementary Structural Inspection Program
91-197-018(B) - Nacelles - Engine Cowl Attachment
86-37-17(B) - Fuel System - Booster Crossfeed Valve Actuator

Gulfstream Aerospace G150 Series Aeroplanes

ISR-I-24-2018-09-7 - Electrical Power - Upper and Lower Front Relay Box Replacement
28-12-06-18 - Inboard Vent Holes - Inspection

Turbine Engines

General Electric Turbine Engines - CF34 Series

2018-19-22 - High-Pressure Turbine (HPT) Front Rotating Air Seals - Replacement

Equipment

Seats and Berths

2018-0223 - Equipment / Furnishing - Seat Energy Absorber Assembly - Modification