



Australian Government  
Civil Aviation Safety Authority

## CASA AD Biweekly 22/2025 – 6 November 2025

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 24 October and 6 November 2025.

### **Rotorcraft**

#### **Airbus Helicopters H160 Series**

2025-0242 - Rotorcraft Flight Manual - Emergency Procedures Section - Amendment, ATA 42 - Integrated Modular Avionics - Ethernet Network - Inspection / Modification  
2022-0168R2 - No longer applicable to H160-B - Rotorcraft Flight Manual - Section Emergency Procedures - Amendment, ATA 42 - Integrated Modular Avionics - Ethernet Network - Inspection

#### **Airbus Helicopters (Eurocopter) AS 350 and EC 130 Series Helicopters**

2025-0137\_Correction - Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment

#### **Airbus Helicopters Deutschland (Eurocopter) MBB-BK 117 Series Helicopters**

2022-0168R2 - Rotorcraft Flight Manual - Section Emergency Procedures - Amendment, ATA 42 - Integrated Modular Avionics - Ethernet Network - Inspection

#### **Airbus Helicopters Deutschland (Eurocopter) EC 135 Series Helicopters**

2022-0168R2 - Rotorcraft Flight Manual - Section Emergency Procedures - Amendment, ATA 42 - Integrated Modular Avionics - Ethernet Network - Inspection

#### **Airbus Helicopters (Eurocopter) SA 360 and SA 365 Series Helicopters**

2025-0239 - Rotors Flight Control - Upper Ball Bearing End of the Main Rotor Servo-Controls - Inspection

### **Above 5700 kgs**

#### **Airbus A319, A320 and A321 Series Aeroplanes**

2025-0234 - Fire Protection - Fire Panel - Inspection  
2025-0237 - Equipment / Furnishings - 80 VU Rack Attachments - Inspection / Repair  
2025-0207R1 - Fuselage - Seat Rail Connections Nylon Bushes - Replacement

#### **Airbus A330 Series Aeroplanes**

2025-0241 - Navigation - Angle of Attack Backplate - Repair

#### **ATR-GIE Avions de Transport Regional ATR 42 Series Aeroplanes**

2025-0223R1 - Parking, Mooring and Storage - Mooring Procedure - Prohibition

#### **ATR-GIE Avions de Transport Regional ATR 72 Series Aeroplanes**

2025-0223R1 - Parking, Mooring and Storage - Mooring Procedure - Prohibition

#### **Bombardier BD-700 Series Aeroplanes**

CF-2025-53 - Flight Controls - Incorrect Airplane Flight Manual (AFM) Approach Speed Adder and Landing Distance Factors for SLAT FAIL (Caution) Crew-Alerting System (CAS) Message Non-Normal Procedure

## **De Havilland Canada (Bombardier) DHC-8 Series Aeroplanes**

CF-2025-52 - Navigation - 5G C-Band wireless Broadband Interference with Radio Altimeter System when operating in the contiguous United States of America (U.S.) airspace

CF-2025-54 - Navigation - 5G C-Band wireless Broadband Interference with Radio Altimeter System when operating in Canadian airspace affected by 5G C-Band wireless signals

CF-2025-55 - Navigation - 5G C-Band wireless Broadband Interference with Radio Altimeter System when operating in Canadian airspace

## **Embraer ERJ 190 Series Aeroplanes**

2018-07-01R1 - Inspection of the Pintle Pins of the MLG Shock Strut

## **Fokker Services F27 Series Aeroplanes**

2025-0240 - Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2, Airworthiness Limitation Items and Safe Life Items - Amendment

## **Fokker Services F50 (F27 Mk 50) Series Aeroplanes**

2025-0240 - Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2, Airworthiness Limitation Items and Safe Life Items - Amendment

## **Turbine Engines**

### **CFM International Turbine Engines - LEAP-1A and LEAP-1C Series**

2025-0243 - Engine - Forward Outer Seal, High-Pressure Compressor Stages 6-10 Compressor Rotor Spools and High-Pressure Turbine Rotor Stage 1 Disks - Replacement

2025-0246 - Engine - Non-Synchronous Vibration During Engine Operation - Monitoring / Replacement