



CASA AD Biweekly 3/2019 – 7 February 2019

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 25 January and 7 February 2019.

Rotorcraft

Airbus Helicopters (Eurocopter) AS 332 Series Helicopters

2019-0021 (Correction) - Rotorcraft Flight Manual / Emergency Procedures - Amendment; and
Navigation - Attitude and Heading Reference System - Modification

Airbus Helicopters Deutschland (Eurocopter) BO105 Series Helicopters

2019-0024 - Airworthiness Limitation Section - TT-Straps - Storage Life Limit

Airbus Helicopters (Eurocopter) SA 360 and SA 365 Series Helicopters

2014-0159R1 - Fuselage - 9 Degree Frame - Inspection
2014-0162R2 - Fuselage - 9 Degree Upper Frame - Inspection

Bell Helicopter Textron Canada (BHTC) 429 Series Helicopters

CF-2019-03 - Time Limits/Maintenance Checks - New Airworthiness Life Limitations

Helicopteres Guimbal Cabri G2 Series Helicopters

2019-0025 - Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment

Leonardo Helicopters (AgustaWestland) AW169 Series Helicopters

2019-0019 - Tail Rotor - Actuator Input Lever - Inspection

Leonardo Helicopters (AgustaWestland) AB139 and AW139 Series Helicopters

2019-0022 (Correction) - Tail Rotor - Duplex Bearings - Replacement

Leonardo Helicopters (AgustaWestland) AW169 Series Helicopters

2019-0022 (Correction) - Tail Rotor - Duplex Bearings - Replacement
2019-0023 - Tail Rotor - Tail Rotor Servo Actuator - Inspection

Leonardo Helicopters (AgustaWestland) AW189 Series Helicopters

2019-0019 - Tail Rotor - Actuator Input Lever - Inspection
2019-0022 (Correction) - Tail Rotor - Duplex Bearings - Replacement
2019-0023 - Tail Rotor - Tail Rotor Servo Actuator - Inspection

Below 5700 kgs

ASI Aviation (Reims) F406 Series Aeroplanes

AD/F406/16 - Avionics Bus Circuit Breaker Switches - CANCELLED
2019-0015 - Electrical Power - Circuit Breaker Switches - Inspection / Replacement
2019-0016 - Flight Controls - Rudder Control Pedal Torque Tubes - Inspection / Replacement

Blanchair (Eagle / Bellanca) DW-1 Series Aeroplanes

AD/DW-1/1 - Elevator Push Tube - Replacement

Pacific Aerospace 750XL Series Aeroplanes

DCA/750XL/32B - NLG and MLG Attachment Bolts - Inspection

DCA/750XL/33A - Aileron Pivot Fork Assembly - Inspection

DCA/750XL/34 - Port Wing Internal Tank Abrasion - Inspection

DCA/750XL/35 - Engine Mount Chafing - Inspection

DCA/750XL/36 - Fuel Pickup Assembly and Wing Spar Web - Inspection

Textron Aviation (Cessna) 208 Series Aeroplanes

AD/CESSNA 208/18 Amdt 1 - Emergency Power Lever Shear Wire

Above 5700 kgs

Airbus A319, A320 and A321 Series Aeroplanes

2019-0012 - Wings - Flap Parts - Inspection / Replacement (Wrong Material)

Airbus A330 Series Aeroplanes

2018-0144R1 - Fuselage - Emergency Locator Transmitter Antenna - Inspection

2019-0026 - Wings - Slat Tracks Number 10 - Inspection / Replacement

2019-0027 - Oxygen - Oxygen Crew and Courier Distribution System Flexible Hoses - Inspection / Replacement

Boeing 787 Series Aeroplanes

2019-01-01 (Correction) - Extended Operations (ETOPS) - Flight Manual Revision

Bombardier CL-600 Series Aeroplanes

CF-2015-28R2 - Equipment/Furnishings - Damaged Decompression Window Louver Panel Assemblies and Detached Blowout Panels

CF-2019-04 - Cold Weather Operations - Introduction of Low Temperature Ground Wing Anti-Ice System

Bombardier DHC-8 Series Aeroplanes

CF-2009-11R3 - Failure of the Main Landing Gear Stabilizer Braces

Turbine Engines

CFM International Turbine Engines - CFM56 Series

2019-0018 - Engine - Fan Blades - Inspection

Pratt and Whitney Canada Turbine Engines - PT6B Series

CF-2019-05 - Engine Control - Fuel Control Unit (FCU) Galvanic Corrosion Contamination