



CASA AD Biweekly 5/2020 – 5 March 2020

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 21 February and 5 March 2020.

Rotorcraft

Airbus Helicopters (Eurocopter) EC 175 Series Helicopters

2020-0042 - Main Rotor Drive - Main Gearbox Top Sensor / Main Rotor Mast Lubrication System - Inspection

Bell Helicopter Textron 204 Series Helicopters

2020-0039 - Fire Protection - Hand-held Fire Extinguishers - Replacement

Bell Helicopter Textron 205 Series Helicopters

2020-0039 - Fire Protection - Hand-held Fire Extinguishers - Replacement

Bell Helicopter Textron 212 Series Helicopters

2020-0039 - Fire Protection - Hand-held Fire Extinguishers - Replacement

Bell Helicopter Textron 214B and 214B-1 Series Helicopters

2020-0039 - Fire Protection - Hand-held Fire Extinguishers - Replacement

Bell Helicopter Textron Canada (BHTC) 222 and 230 Series Helicopters

2020-0039 - Fire Protection - Hand-held Fire Extinguishers - Replacement

Bell Helicopter Textron 412 and Leonardo Helicopters (Agusta) AB412 Series Helicopters

2020-0039 - Fire Protection - Hand-held Fire Extinguishers - Replacement

Sikorsky Aircraft Corporation S-76 Series Helicopters

2020-0039 - Fire Protection - Hand-held Fire Extinguishers - Replacement

Sikorsky Aircraft Corporation S-92 Series Helicopters

2020-0039 - Fire Protection - Hand-held Fire Extinguishers - Replacement

Below 5700 kgs

Pipistrel Vertical Solutions Virus SW 121 Series Aeroplanes

2020-0045 - Fuel - Fuel Pressure Sensor - Inspection / Replacement

Textron Aviation (Cessna) 210 Series Aeroplanes

2020-03-16 - Carry-Thru Spar Lower Cap

Above 5700 kgs

Airbus A319, A320 and A321 Series Aeroplanes

AD/A320/89 Amdt 1 - Fuselage Frames 38 to 41 - CANCELLED
2020-0034 - Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 4 - System Equipment Maintenance Requirements - Implementation
2020-0036 - Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 - Damage Tolerant Airworthiness Limitation Items - Implementation
2015-0036R2 - Fuselage - Fuselage Skin Repairs - Inspection
2020-0037 (Correction) - Fuselage - Frame Foot Coupling at Frame 43 - Inspection / Repair
2020-0040 - Fuselage - Overwing Emergency Exit Cut-Outs in Section 15 - Modification

Airbus A330 Series Aeroplanes

2019-0291R1 - Fuel - Fuel Pump - Inspection

Boeing 737 Series Aeroplanes

2020-03-10 - Lower Aft Wing-to-Body Fairing Panel 194E

Boeing 757 Series Aeroplanes

2020-01-18 (Correction) - Airworthiness Limitations and Certification Maintenance Requirements - Revision

Boeing 787 Series Aeroplanes

2020-03-22 - Wings - Frame Tie Rod Assemblies

Turbine Engines

CFM International Turbine Engines - CFM56 Series

2020-0044 - Engine - High-Pressure Turbine Inner Stationary Seal - Inspection

Pratt and Whitney Turbine Engines - PW1500 and PW1900 Series

2019-16-15 - Airworthiness Limitations Section Revision - High Pressure Compressor Hub
2019-21-11 - Low-Pressure Compressor (LPC) Inlet Guide Vane and the LPC Rotor 1
2020-04-01 - Turbine Engine Oil System - LP10 Oil Supply Tube

Rolls Royce Turbine Engines - RB211 TRENT 900 Series

2020-0041 - Engine - Intermediate Pressure Compressor Rotor Shaft - Inspection

Safran Helicopter Engines (Turbomeca) Turbine Engines - Arriel Series

2020-0046 - Engine Fuel & Control - Full Authority Digital Engine Control B / Digital Engine Control Unit - Inspection / Replacement

Safran Helicopter Engines (Turbomeca) Turbine Engines - Arrius Series

2020-0033 - Engine Fuel & Control - Hydro-mechanical Metering Unit / Drive Link Splines - Inspection