



Australian Government
Civil Aviation Safety Authority

CASA AD Biweekly 6/2020 – 19 March 2020

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 6 March and 19 March 2020.

Rotorcraft

Airbus Helicopters (Eurocopter) AS 332 Series Helicopters

2020-0061 - Windows - Jettisoning System - Modification

Airbus Helicopters (Eurocopter) EC 175 Series Helicopters

2020-0049 - Fuel System - Fuel Tank - Inspection/Replacement

2020-0057 - Rotorcraft Flight Manual - Supplements / One Engine Inoperative Performance Limitations - Amendment

Airbus Helicopters (Eurocopter) EC 225 Series Helicopters

2020-0061 - Windows - Jettisoning System - Modification

Bell Helicopter Textron 412 and Leonardo Helicopters (Agusta) AB412 Series Helicopters

2020-0062-E - Tail Rotor - Hub / Blade Assembly - Replacement

Leonardo Helicopters (AgustaWestland) AW169 Series Helicopters

2020-0048 - Tail Rotor - Tail Rotor Servo Actuator / Duplex Bearing - Inspection / Check / Modification

Leonardo Helicopters (AgustaWestland) AW189 Series Helicopters

2020-0048 - Tail Rotor - Tail Rotor Servo Actuator / Duplex Bearing - Inspection / Check / Modification

Robinson Helicopter Company R44 Series Helicopters

2020-05-11 - Agricultural Spray System (STC SR00286BO) Elbow Pump Fitting

Below 5700 kgs

Daher Aircraft Design (Quest Aircraft Design) Kodiak 100 Series Aeroplanes

2020-04-13 - POH/AFM Revision - Obstacle Landing Distance Table

Viking Air DHC-6 (Twin Otter) Series Aeroplanes

CF-2020-05 - Wings - Cracking and Corrosion of Aileron Internal Structure

Above 5700 kgs

Airbus A319, A320 and A321 Series Aeroplanes

2020-0052 - Fuselage - Satellite Communications Antenna Doubler - Inspection / Replacement

2020-0053 - Nacelles / Pylons - Engine Pylon Nose Fire Seals - Inspection / Replacement

Airbus A330 Series Aeroplanes

2020-0054 - Flight Controls - Spoiler Servo Control / Hydraulic Locking Function - Operational Test

Airbus A380 Series Aeroplanes

2020-0058 - Equipment / Furnishings - Emergency Locator Transmitter Protection - Modification

Boeing 747 Series Aeroplanes

2020-04-11 - Fuselage Upper Skin Lap Splice - Inspection

Boeing 777 Series Aeroplanes

2020-04-19 - Mode Control Panel (MCP) - Replacement

Bombardier BD-700 Series Aeroplanes

CF-2020-07 - Lights - Emergency Light Battery Pack Corrosion

Bombardier CL-600 Series Aeroplanes

CF-2020-03 - Fuel System - Primary Ejector Fuel Feed Flexible Hoses Inner Tube Cracking

De Havilland Canada (Bombardier) DHC-8 Series Aeroplanes

CF-2020-06 - Standard Practices/Structures - Introduction of Barrel Nut Inspections

Turbine Engines

Rolls Royce (Allison) Turbine Engines - 250 Series

AD/AL 250/91 - Engine Compressor Module - Removal from Service

Rolls Royce Turbine Engines - RB211 Series

2020-0059 - Engine - Low Pressure Turbine Stage 1 Discs - Life Reduction