



Australian Government
Civil Aviation Safety Authority

CASA AD Biweekly 12/2025 – 19 June 2025

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 6 June and 19 June 2025.

Rotorcraft

Bell Helicopter Textron Canada (BHTC) 429 Series Helicopters

CF-2025-29 - Tail Rotor Blade Abrasion Strip Cracks

Leonardo Helicopters (AgustaWestland) A109 Series Helicopters

2025-0131 - Main Rotor - Swashplate Nuts - Inspection / Reinstallation

Leonardo Helicopters (AgustaWestland) A119 Series Helicopters

2025-0131 - Main Rotor - Swashplate Nuts - Inspection / Reinstallation

Robinson Helicopter Company R44 Series Helicopters

2025-11-07 - Forward Flex Plate Assembly, Yoke and Flex Plate Bolts - Inspection / Replacement

Below 5700 kgs

Textron Aviation (Beechcraft) 33 and 35-33 (Debonair/Bonanza) Series Aeroplanes

AD/BEECH 33/41 Amdt 6 - Wing Bolt, Nut and Fitting

Textron Aviation (Beechcraft) 35 (Bonanza) Series Aeroplanes

AD/BEECH 35/67 Amdt 6 - Wing Bolt, Nut and Fitting

Textron Aviation (Beechcraft) 55, 58 and 95-55 (Baron) Series Aeroplanes

AD/BEECH 55/79 Amdt 7 - Wing Bolt, Nut and Fitting

Above 5700 kgs

Airbus Canada BD-500 Series Aeroplanes

CF-2023-47R1 - Navigation - Minimum Equipment List (MEL) Item Prohibitions in the Presence of 5G C-Band Wireless Broadband Interference

Boeing 787 Series Aeroplanes

2025-06-13 Correction - Floor Beam Side-of-Body Fittings

Bombardier BD-700 Series Aeroplanes

CF-2025-28 - Doors - Baggage Doorstop Fittings - Improperly Torqued Bolts

Textron Aviation (Cessna) 560 (Citation V) and 560XL Series Aeroplanes

2025-11-09 - Fire Extinguishing Bottle Wiring

Turbine Engines

General Electric Turbine Engines - CF34 Series

2025-12-08 - Combustion Chamber Assembly - Reduction in Cyclic Life

International Aero Engines LCC (IAE) PW1100/PW1400 Series

2018-13-03 - Engine Fan Hub

2018-21-10 - Rear High-Pressure Compressor (HPC) Rotor Hub Knife Edge Seal

2018-22-02 - High-Pressure Compressor (HPC) Front Hub

2019-06-01 - Low-Pressure Turbine (LPT) 1st and 3rd-Stage Disks - Removal From Service

2019-25-01 - LPT 3rd-stage Blades

2020-05-28 - Main Gearbox Assembly

2020-06-02 - Turbine Piston Seal

2020-08-04 - Low Pressure Turbine 3rd Stage Blades - Replacement

2021-19-10 - High Pressure Turbine 1st Stage and 2nd Stage Disks - Removal from Service

2023-16-07 - Ultrasonic Inspection of the HPT Hubs

2023-20-11 - Forward and Aft Knife Edge Seals

2024-05-11 - Ultrasonic Inspection of the HPT Hubs

2024-06-14 - HPC 2nd Stage Rotors and HPC 4th Stage Rotors Knife-edge Seals and Abrasive Coating of the Rear Wing 4th Stage Rotor

2024-14-04 - Low Pressure Compressor 1st Stage Integrally Bladed Rotor