



## CASA AD Biweekly 15/2020 – 23 July 2020

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 10 July and 23 July 2020.

### **Rotorcraft**

#### **Airbus Helicopters (Eurocopter) EC 175 Series Helicopters**

2020-0152 - Doors - Cargo Door Handle Spring - Replacement  
2020-0164 - Fuselage - Pylon Skin - Inspection

#### **Airbus Helicopters (Eurocopter) SA 360 and SA 365 Series Helicopters**

2020-0156 - Main Rotor Drive - Main Gearbox Magnetic Plug and Oil Filter - Inspection / Modification

### **Below 5700 kgs**

#### **Daher Aircraft Design (Quest Aircraft Design) Kodiak 100 Series Aeroplanes**

2020-13-01 - Nose Landing Gear Fork

#### **Pilatus P3 Series Aeroplanes**

HB-2020-006 - Fuselage - Fuselage to Horizontal Tail Fittings - Inspection / Replacement

### **Above 5700 kgs**

#### **Airbus A319, A320 and A321 Series Aeroplanes**

2020-0153 - Fuselage - Rear Fuselage Clips, Shear Webs and Angles - Replacement  
2020-0155 - Communications / Cabin Systems - Removable Display Unit and Display Docking Station Attachment Interface - Operational Restriction / Inspection

#### **Airbus A330 Series Aeroplanes**

2020-0155 - Communications / Cabin Systems - Removable Display Unit and Display Docking Station Attachment Interface - Operational Restriction / Inspection

#### **Airbus A380 Series Aeroplanes**

2020-0157 - Landing Gear - Gravity Extension System - Inspection / Modification  
2020-0162 - Pneumatic - Pylon / Wing Interface Bleed Duct and Fuel Pipe - Inspection

#### **Boeing 737 Series Aeroplanes**

2020-14-09 - Removal of Kathon FP 1.5 Biocide

#### **Bombardier and MHI RJ Aviation CL-600 Series Aeroplanes**

CF-2020-24 - Navigation - Inertial Reference System (IRS) / Flight Management System (FMS) - Wrong Magnetic Heading Displayed due to Outdated Magnetic Variation (MagVar) Tables  
CF-2014-07R1 - Cracking of Skin Panels and Skin Splice Joints and Angles at Stringers 6 and 20 Between Fuselage Station 409.00 and 589.00

### **Pilatus Aircraft PC-24 Series Aeroplanes**

2020-0158 - Air Vehicle Wiring - Electrical Harness Installation - Modification  
2020-0160 - Air Conditioning - Cockpit and Cabin Evaporator Filters - Replacement

### **Yabora Industria Aeronautica (Embraer) EMB-135 and EMB-145 Series Aeroplanes**

2020-07-02 - FADEC Software Update

### **Yabora Industria Aeronautica (Embraer) ERJ 190 Series Aeroplanes**

2020-07-01 - Aircraft Flight Manual amendment to incorporate a new Limitation and to amend the Normal Procedures section to limit the Engine N1 Setting for Flights Above 33000 Feet

## **Turbine Engines**

### **General Electric Turbine Engines - CF6 Series**

AD/CF6/60 - High Pressure Compressor Case - CANCELLED

### **Safran Helicopter Engines (Turbomeca) Turbine Engines - Arriel Series**

2020-0151-E - Engine - Module 03 / Stage 2 High Pressure Turbine Disc - Replacement