



Australian Government
Civil Aviation Safety Authority

CASA AD Biweekly 2/2024 – 25 January 2024

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 12 January and 25 January 2024.

Rotorcraft

Airbus Helicopters (Eurocopter) AS 350 and EC 130 Series Helicopters

2024-0018 - Indicating / Recording Systems - Control Unit - Inspection

Airbus Helicopters (Eurocopter) EC 120 Series Helicopters

2024-0018 - Indicating / Recording Systems - Control Unit - Inspection

Below 5700 kgs

Diamond Aircraft Industries DA 42 and DA 62 Series Aeroplanes

CF-2024-02 - Stabilizers - Horizontal Stabilizer - Incorrect Torque Specified for Attachment Bolts

Above 5700 kgs

Airbus A319, A320 and A321 Series Aeroplanes

2024-0022 - Landing Gear - Nose Landing Gear - Repair Assessment

Airbus A330 Series Aeroplanes

2024-0011 - Time Limits / Maintenance Checks - Damage Tolerant Airworthiness Limitation Items - ALS Part 2 - Amendment

2024-0014 - Time Limits / Maintenance Checks - System Equipment Maintenance Requirements - ALS Part 4 - Amendment

2024-0016 - Flight Controls - Trimmable Horizontal Stabilizer Actuator / Electric Load Sensing Device - Modification

2024-0023 - Equipment/Furnishings - Galley 4 Aft Bulkhead Cover Panel - Replacement

ATR-GIE Avions de Transport Regional ATR 42 Series Aeroplanes

2024-0025 - Placards and Markings - Cargo Height Limitation - Implementation (EASA STC 10069551 Rev.1)

ATR-GIE Avions de Transport Regional ATR 72 Series Aeroplanes

2024-0025 - Placards and Markings - Cargo Height Limitation - Implementation (EASA STC 10069551 Rev.1)

Boeing 737 Series Aeroplanes

2024-02-51 - Potential In-Flight Loss of Mid Cabin Door Plug

Dassault Aviation Falcon 7X Series Aeroplanes

2024-0021 - Wings - Ailerons - Inspection

De Havilland Canada (Bombardier) DHC-8 Series Aeroplanes

CF-2024-01 - Landing Gear - Main Landing Gear - Brake Fuse/Shuttle Valve Assembly - Failure Caused by Assembly Error

Embraer ERJ 190 Series Aeroplanes

2023-01-01R1 - AFM Amendment - Operational Limitations

Embraer EMB-505 (Phenom 300) Series Aeroplanes

2023-07-01_Correction - Embraer EMB-505 - Installation of Structural Reinforcements in Floor

Turbine Engines

CFM International Turbine Engines - LEAP-1A and LEAP-1C Series

2024-0026 - Engine - High Pressure Turbine - Rotor Interstage Seal - Replacement

General Electric Turbine Engines - GE90 Series

2023-26-07 - HPT Stage 1 and Stage 2 Disks, Forward HPT Rotor Seals, Interstage HPT Seals, Stages 7-9 Compressor Rotor Spools - Inspection/ Replacement

Equipment

Flight and Engine Instruments (including Autopilots)

2024-0024 - Navigation - Digital Air Data Computer - Replacement