



CASA AD Biweekly 24/2011 - 1 December 2011

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 17 November and 1 December 2011.

Rotorcraft

Bell Helicopter Textron Canada (BHTC) 206 and Agusta Bell 206 Series Helicopters

CF-2011-44 - Main Rotor Blade

Above 5700 kgs

Embraer EMB-135 and EMB-145 Series Aeroplanes

2011-11-01 - Tail Boom Lightning Protection

Gulfstream (Grumman) G1159 and G-IV Series Aeroplanes

2011-24-02 - Fire Extinguisher Bottle - Fixed

Piston Engines

Rotax Piston Engines

2011-0224-E - Engine - Crankshaft - Inspection

Teledyne Continental Motors Piston Engines

2011-25-51 - Replacing CMI Starter Adapters due to Fractures in Shaft Gears

Turbine Engines

AlliedSignal (Lycoming) Turbine Engines - ALF502 and LF507 Series

2011-24-11 - Removal of Second Stage High Pressure Compressor (HPC2) Discs due to Cracking

General Electric Turbine Engines - CF6 Series

AD/CF6/74 Amdt 1 - High Pressure Compressor Spool Shaft Stage 14 Disc

Rolls Royce Turbine Engines - RB211 Series

2011-0221R1 - Engine - Intermediate Pressure Compressor Rotor Shaft and Balance Weights - Inspection / Modification

Equipment

Seats and Berths

2011-008-E - Inspection of Ejection Seat Drogue Shackle Connection to Scissor Shackle