



CASA AD Biweekly 14/2011 - 14 July 2011

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 1 July and 14 July 2011.

Rotorcraft

Bell Helicopter Textron Canada (BHTC) 206 and Agusta Bell 206 Series Helicopters

CF-2011-19 - Incorrect Assembly of Hydraulic Servo Actuators

Bell Helicopter Textron Canada (BHTC) 407 Series Helicopters

CF-2011-17 - Incorrect Assembly of Hydraulic Servo Actuators

Bell Helicopter Textron 427 Series Helicopters

CF-2011-17 - Incorrect Assembly of Hydraulic Servo Actuators

Eurocopter AS 332 (Super Puma) Series Helicopters

2009-0271R1 - Equipment & Furnishings - Hydraulic Hoist Cable - Limitation / Modification

Eurocopter AS 350 (Ecureuil) Series Helicopters

2011-0116 - Fuselage - Tail Boom / Fenestron Junction Frame - Inspection

Eurocopter BK 117 Series Helicopters

2011-0131 - Optional Equipment - External Rescue Hoist System - Deactivation

Eurocopter SA 360 and SA 365 (Dauphin) Series Helicopters

AD/DAUPHIN/95 - Main Gearbox Casing - Corrosion - CANCELLED

2011-0127 - Main Rotor Drive - Main Gearbox Casing - Inspection / Repair

Kawasaki BK 117 Series Helicopters

TCD-7745-1-2011 - Instrument Control Panel BARO Adjustment Knobs

Schweizer (Hughes) 269 Series Helicopters

2011-12-16 - Tailboom After Cluster Fitting Strut Locknut

Below 5700 kgs

Aerospatiale (Socata) TBM 700 Series Aeroplanes

2011-0130 - Navigation - Standby Compass Lighting - Modification

DHC-3 (Otter) Series Aeroplanes

2011-12-02 - Airspeed Limitations for aircraft with a Honeywell TPE331-10 or -12JR turboprop engine installed per Supplemental Type Certificate (STC) SA09866SC

Fairchild (Swearingen) SA226 and SA227 Series Aeroplanes

AD/SWSA226/38 Amdt 1 - Elevator Return Spring Location - Modification - CANCELLED

Pacific Aerospace Corporation Cresco Series Aeroplanes

DCA/CRESCO/3B - Elevator Tip Rib - Inspection

Above 5700 kgs

Airbus Industrie A319, A320 and A321 Series Aeroplanes

2011-0120R1 - Fuselage - Nuts - Inspection / Replacement

2011-0121R1 - Wings - Nuts - Inspection / Replacement

AMD Falcon 50 and 900 Series Aeroplanes

2010-0080 - Time Limits/Maintenance Checks - Airworthiness Limitations Section - Revision

Boeing 737 Series Aeroplanes

2011-12-13 (Correction) - Testing of the Stabilizer Takeoff Warning Switches

Bombardier (Canadair) CL-600 (Challenger) Series Aeroplanes

CF-2011-16 - Nuisance Indication of Failed Wing Anti-Ice System

CF-2011-18 - Integrated Drive Generator Wire Chafing in Aft Equipment Bay

Bombardier (Boeing Canada/De Havilland) DHC-8 Series Aeroplanes

CF-2011-15 - Inability to Deflate the Seal and Open the Airstair Door

Turbine Engines

Turbomeca Turbine Engines - Arriel Series

2011-0128-E - Engine Fuel & Control - Hydro-Mechanical Metering Unit (HMU) - Inspections / Replacement

Equipment

Oxygen Systems

2011-0090R1 - Oxygen - Oxygen Mask Regulator Inflatable Harness - Identification / Replacement