



CASA AD Biweekly 26/2011 - 31 December 2011

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 15 December and 31 December 2011.

Rotorcraft

Bell Helicopter Textron Canada (BHTC) 206 and Agusta Bell 206 Series Helicopters

AD/BELL 206/130 Amdt 3 - Main Landing Gear Cross Tubes - CANCELLED
CF-1995-17R1 - Main Landing Gear Cross Tubes

Bell Helicopter Textron Canada (BHTC) 407 Series Helicopters

CF-2011-17R1 - Incorrect Assembly of Hydraulic Servo Actuators

Bell Helicopter Textron 427 Series Helicopters

CF-2011-17R1 - Incorrect Assembly of Hydraulic Servo Actuators

Bell Helicopter Textron 412 Series Helicopters

2011-0247 - Main Rotor - Collective Lever - Inspection / Replacement

Eurocopter AS 350 (Ecureuil) Series Helicopters

2011-0244-E - Lights - Position Strobe Light - Inspection / Deactivation

Eurocopter AS 355 (Twin Ecureuil) Series Helicopters

2011-0244-E - Lights - Position Strobe Light - Inspection / Deactivation

Above 5700 kgs

Airbus Industrie A330 Series Aeroplanes

2011-0242 - Windows - Fixed Windows / Windshield Heating Connectors - Inspection / Replacement

Airbus Industrie A380 Series Aeroplanes

2011-0248 - Fuel - Feed Tank 1 and/or 4 Main and Standby Pump Fault Light Flickering - Operational Procedure

AMD Falcon 50 and 900 Series Aeroplanes

2011-0246 - Time Limits and Maintenance Checks - Airworthiness Limitations - Amendment / Implementation

Boeing 737 Series Aeroplanes

AD/B737/297 Amdt 2 - De-Icing Fluids and Main Wheel Well Electrical Connectors

Boeing 767 Series Aeroplanes

AD/B767/243 - Engine Indication and Crew Alerting System - CANCELLED

Boeing 777 Series Aeroplanes

2011-26-03 - Prevention of Electrical Arcing on the Fuel Tank Boundary Structure or Inside the Main and Center Fuel Tanks

Bombardier (Canadair) CL-600 (Challenger) Series Aeroplanes

CF-2011-45 - Horizontal Stabilizer Trim Actuator Attachment Pins and Trunnions Not Serialized

Bombardier (Boeing Canada/De Havilland) DHC-8 Series Aeroplanes

CF-2011-46 - Burnt Alternating Current Wire Bundle Under Floor - Cockpit Door Area

Embraer ERJ-170 Series Aeroplanes

2011-12-01 - Escape Slide Deployment Failures

Embraer ERJ-190 Series Aeroplanes

2011-12-02 - Escape Slide Deployment Failures

Learjet 45 Series Aeroplanes

2011-25-03 - Main Landing Gear Actuator End Cap Fatigue Cracking

Piston Engines

Engines - General

2011-26-07 - Champion Aerospace (formerly Unison Industries) (Slick) Magneto

SMA Piston Engines

AD/SMA/4 - Air Inlet Manifold Hose Clamps - CANCELLED

2008-0078R1 - Engine Air - Air Inlet Manifold Hose Clamps - Inspection

Teledyne Continental Motors Piston Engines

2011-26-07 - Champion Aerospace (formerly Unison Industries) (Slick) Magneto

Turbine Engines

Engines - General

2011-26-07 - Champion Aerospace (formerly Unison Industries) (Slick) Magneto

AlliedSignal (Garrett/AiResearch) Turbine Engines - TFE731 Series

AD/TFE 731/33 Amdt 1 - LPT Stage 1 Nozzle and Disks

Rolls Royce Turbine Engines - RB211 Series

2011-0243 - Engine - Low Pressure (LP) Fuel Tubes and Clips - Inspection

Turbomeca Turbine Engines - Arriel Series

2011-0249 - Engine Fuel & Control - Digital Engine Control Unit (DECU) - Identification / Replacement

Equipment

Radio Communication and Navigation Equipment

2011-0239 - Navigation - Radio Altimeter Indicator- Modification