



CASA AD Biweekly 13/2014 – 26 June 2014

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 13 June 2014 and 26 June 2014.

Rotorcraft

Agusta A109 Series Helicopters

2014-0150 - Stabilizers - Vertical Fin Vibration Absorber - Inspection / Removal

Bell Helicopter Textron 204 Series Helicopters

2014-12-04 - Main Rotor Hub Grip Tangs - Inspection

Bell Helicopter Textron 205 Series Helicopters

2014-12-04 - Main Rotor Hub Grip Tangs - Inspection

Bell Helicopter Textron 212 Series Helicopters

2014-12-04 - Main Rotor Hub Grip Tangs - Inspection

Eurocopter AS 350 (Ecureuil) and EC 130 Series Helicopters

2014-0145R1 - Fuselage - Tail Boom / Fenestron Junction Frame - Inspection

Eurocopter SA 360 and SA 365 (Dauphin) Series Helicopters

2012-0170R2 - Time Limits and Maintenance Checks - Tail Rotor Gearbox (TGB) Oil Level and Magnetic Chip Detector - Inspection & Tail Rotor - Pitch Control Rod Bearing - Inspection / Replacement

Below 5700 kgs

Pacific Aerospace 750XL Series Aeroplanes

DCA/750XL/16A - Fin Forward Pickup - Inspection

Above 5700 kgs

Airbus Industrie A319, A320 and A321 Series Aeroplanes

AD/A320/226 - Trimmable Horizontal Stabilizer Actuator - CANCELLED

2014-0146 - Fuselage - Frame 24 at Stringer 17/18 - Inspection

2014-0147 - Flights Controls - Trimmable Horizontal Stabilizer Actuator - Inspection

Airbus Industrie A330 Series Aeroplanes

2014-0148 - Fire Protection / Lights / Pneumatic / Fuselage - Prevention against Explosion Risks in Section 19 - Modifications

2014-0136 - Fuselage - Frame (FR) 40 / Fuselage Skin Panel Junction - Inspection

2014-0149 - Wings - Center Wing Box Fastener Holes at Frame 40 Vertical Web - Inspection

Boeing 727 Series Aeroplanes

2014-12-10 - Cracking in Stringers or Frames

Bombardier (Canadair) CL-600 (Challenger) Series Aeroplanes

CF-2014-16 - Landing Gear - Alternate Extension System (AES) - Incorporation of New Certification Maintenance Requirement

CF-2014-17 - Additional Limitation for Landing/Taxi Light Operations on Ground due to Potential Fuel Leakage

CF-2014-19 - Engine Exhaust - Engine Thrust Reverser Actuator Attachment Structure Failure

Bombardier (Boeing Canada/De Havilland) DHC-8 Series Aeroplanes

CF-2014-18 - Main Landing Gear - Improperly Stowed Parking Brake Hand Pump Lever in Right Hand Side Nacelle

Embraer EMB-135 and EMB-145 Series Aeroplanes

2014-06-01 - Ribbon Heater for Pitot Pressure Lines

Fokker F27 Series Aeroplanes

2014-0151 - Time Limits / Maintenance Checks - Maintenance Requirements - Implementation

Fokker F50 (F27 Mk 50) Series Aeroplanes

2014-0151 - Time Limits / Maintenance Checks - Maintenance Requirements - Implementation

Turbine Engines

Rolls Royce Turbine Engines - RB211 TRENT 700 Series

2014-0152 - Engine - Intermediate Pressure Compressor Rotor Shaft and Balance Weights - Inspection / Modification

Rolls Royce Turbine Engines - RB211 TRENT 900 Series

2014-0152 - Engine - Intermediate Pressure Compressor Rotor Shaft and Balance Weights - Inspection / Modification

Equipment

Oxygen Systems

2014-0142R1 - Oxygen - Oxygen Mask Regulator Inflatable Harness / Inflation Hose - Identification / Replacement