



CASA AD Biweekly 13/2017 – 29 June 2017

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 16 June and 29 June 2017.

Rotorcraft

Airbus Helicopters (Eurocopter) AS 332 Series Helicopters

2017-0111 - Time Limits / Maintenance Checks - Main Gearbox Particle Detector / Oil Filter / Oil Cooler - Inspection, and Main Rotor Drive - Epicyclic Module - Replacement / Modification / Reduced Service

Airbus Helicopters (Eurocopter) AS 350 and EC 130 Series Helicopters

2017-0109 (Correction) - Electrical Power - Starter Generator and Brushes - Inspection / Replacement
2017-0114 - Stabilizers - Vertical Fin - Inspection

Airbus Helicopters (Eurocopter) AS 355 Series Helicopters

2017-0114 - Stabilizers - Vertical Fin - Inspection

Airbus Helicopters (Eurocopter) EC 225 Series Helicopters

2017-0111 - Time Limits / Maintenance Checks - Main Gearbox Particle Detector / Oil Filter / Oil Cooler - Inspection, and Main Rotor Drive - Epicyclic Module - Replacement / Modification / Reduced Service

Kawasaki BK 117 Series Helicopters

TCD-8733A-2017 - Hydraulic Module Plate Assembly Attachment Point - Inspection / Modification

Leonardo Helicopters (AgustaWestland) AW169 Series Helicopters

2017-0110 - Landing Gear - Retraction Actuators - Installation / Replacement
2017-0112 - Rotorcraft Flight Manual / Limitations Section - Amendment

Below 5700 kgs

Cessna 400 Series Aeroplanes

PAD/CESSNA 400/120 - Fitting - Wing Attach - Lower Forward Carry Through Spar (L+R)

Above 5700 kgs

Boeing 737 Series Aeroplanes

AD/B737/314 - Cracking Around Heads of Fasteners - CANCELLED
2017-12-07 - Air Conditioning - Left Temperature Control Valve and Cabin Trim Air Modulating Valve - Replacement
2017-12-05 - Fuselage Skin - Cracking Around Fastener Heads - Inspection
2017-13-01 - Fuselage Frame Inboard Chords - Inspection

Boeing 757 Series Aeroplanes

2017-12-12 - Fuselage - Circumferential Splice Plates at Station 900 and Station 1180 - Inspection
2017-12-14 - Fuselage - Frame Webs - Inspection / Modification

Bombardier DHC-8 Series Aeroplanes

CF-2017-21R1 - Engine Ignition - Loss of #2 Engine Auto Relight Function
CF-2015-13R1 - Stabilizers - Cracked Barrel Nut at the Horizontal Stabilizer to Vertical Stabilizer Attachment Joint

Dassault Aviation Falcon 50 and 900 Series Aeroplanes

2017-0106 - Wings - Slat Extension Mechanical Stop Assembly - Inspection

Dassault Aviation Falcon 2000 Series Aeroplanes

2017-0106 - Wings - Slat Extension Mechanical Stop Assembly - Inspection

Fokker Services F100 (F28 Mk 100) Series Aeroplanes

2017-0113 - Equipment / Furnishing - Passenger Service Unit and Overwing Emergency Exit Door - Inspection / Modification

Turbine Engines

Safran Helicopter Engines (Turbomeca) Turbine Engines - Arriel Series

2017-0064R1 - Engine Fuel & Control - Drain Valve Assembly - Inspection / Replacement

Equipment

Electrical Equipment Miscellaneous (including Magnetos)

AD/ELECT/42 Amdt 2 - Bendix Impulse Couplings