



## CASA AD Biweekly 14/2017 – 13 July 2017

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 30 June and 13 July 2017.

### **Rotorcraft**

#### **Airbus Helicopters (Eurocopter) SA 360 and SA 365 Series Helicopters**

AD/DAUPHIN/86 Amdt 3 - Starflex Star Arm End Bushes - CANCELLED  
2008-0165R1 - Rotor(s) - Starflex Star Arm Ends - Check / Replacement  
2017-0116 - Time Limits / Maintenance Checks - Main Gearbox Magnetic Plugs - Inspection, and Main Rotor Drive - Planet Gear Assemblies - Replacement

#### **Bell Helicopter Textron Canada (BHTC) 429 Series Helicopters**

CF-2017-23 - Furnishings/Equipment - Hoist Overload Clutch Slippage or Cable Rupture

#### **Bell Helicopter Textron Canada (BHTC) 430 Series Helicopters**

CF-2017-23 - Furnishings/Equipment - Hoist Overload Clutch Slippage or Cable Rupture

#### **Kawasaki BK 117 Series Helicopters**

TCD-7804A-2017 - Automatic Flight Control System (AFCS)

### **Below 5700 kgs**

#### **Piper PA-28 Series Aeroplanes**

AD/PA-28/94 Amdt 1 - Engine Oil Cooler Hoses - CANCELLED  
2017-14-04 - Engine Oil Cooler Hose Assemblies - Inspection / Replacement

#### **Piper PA-32 (Cherokee Six) Series Aeroplanes**

AD/PA-32/81 Amdt 1 - Engine Oil Cooler Hoses - CANCELLED  
2017-14-04 - Engine Oil Cooler Hose Assemblies - Inspection / Replacement

### **Above 5700 kgs**

#### **Airbus A319, A320 and A321 Series Aeroplanes**

2017-0117 - Wing - Stringer Attachments at Rib 2 to Rib 7 - Modification  
2017-0119 - Landing Gear - Brake Dual Distribution Valve - Modification

#### **ATR-GIE Avions de Transport Regional ATR 42 Series Aeroplanes**

2017-0118 - Electric / Electronic Common Installation - Wire Chafing Behind Cabin Sidewall - Inspection

#### **ATR-GIE Avions de Transport Regional ATR 72 Series Aeroplanes**

2017-0118 - Electric / Electronic Common Installation - Wire Chafing Behind Cabin Sidewall - Inspection

### **Boeing 737 Series Aeroplanes**

2017-13-13 - Fuselage Frame Web at Station (STA) 344 System Penetration Holes between Stringer S-22L and Stringer S-24L - Inspection

### **Boeing 777 Series Aeroplanes**

2017-13-14 - Galley Tripod Mount Assembly - Inspection

### **Bombardier CL-600 Series Aeroplanes**

CF-2017-24 - Horizontal Stabilizer Trim Actuator - Attachment Pins and Trunnions Not Serialized

### **Embraer EMB-505 (Phenom 300) Series Aeroplanes**

2011-05-05 - Attaching Bolts of Balance Mass Weights to Elevators - Replacement  
2012-03-01 - Flight Control Surfaces - Water Accumulation and Drainage  
2014-04-01 - Landing Gear - Brake Assembly - Inspection  
2015-01-01 - Outboard Wing Leading Edge Piccolo Tubes Installation - Inspection  
2016-04-02 (Correction) - Inspection of the Optimized Performance Analyzer (OPERA) Software Configuration and Airplane Flight Manual (AFM) Limitations Section Revision  
2016-05-01 - Passenger Seat Attachment Fittings - Inspection

### **Gulfstream Aerospace G1159, G-IV and GV Series Aeroplanes**

2017-13-11 - Flight Controls - Gust Lock System

## **Turbine Engines**

### **CFM International Turbine Engines - CFM56 Series**

AD/CFM56/15 Amdt 2 - Fuel Filter Cover Attachment Inspection