



Australian Government
Civil Aviation Safety Authority

CASA AD Biweekly 22/2018 – 1 November 2018

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 19 October and 1 November 2018.

Rotorcraft

Airbus Helicopters Deutschland (Eurocopter) MBB-BK 117 Series Helicopters

2018-0225-E - Equipment & Furnishings - Hook Mount Assembly - Inspection
2018-0230 - Integrated Modular Avionics - Aircraft Management Computer Software - Modification

Bell Helicopter Textron UH-1 (All Variants) Series Helicopters

PAD/UH-1/20 - Tail Boom and Fin - Fretting and Cracking

Kawasaki BK 117 Series Helicopters

TCD-9188-2018 - Goodrich Rescue Hoist P/N 44301-10-7 - Hook Mount Assembly Lock Spring System

Robinson Helicopter Company R22 Series Helicopters

DCA/R22/50 - Helipod III Spray System STC 7/21E/9 - Removal from Service
DCA/R22/51 - Helipod NZ Limited STCs - Report of Installation

Robinson Helicopter Company R44 Series Helicopters

DCA/R44/36 - Helipod NZ Limited STCs - Report of Installation

Above 5700 kgs

Airbus A319, A320 and A321 Series Aeroplanes

2018-0218 (Correction) - Wings - Center and Outer Wing Box at Level of Rib 1 Junction - Inspection
2018-0231 - Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 5 - Fuel Airworthiness Limitations - Amendment
2018-0233 - Fuselage - Cargo Compartment Fitting Brackets, Tack and Rivet Holes - Inspection / Repair

Airbus A330 Series Aeroplanes

2018-0226 - Stabilizers - Horizontal Stabilizer Centre Box Top Skin - Inspection / Repair
2018-0227 - Exhaust - Thrust Reverser Latch Beam Gussets - Inspection / Modification
2018-0228 - Power Plant - Engine Air Inlet Cowl Inner Barrel Lower Panels - Inspection / Replacement

Boeing 787 Series Aeroplanes

2018-22-04 - Inboard and Outboard Trailing Edge Flap Rotary Actuators - Inspection / Replacement

Bombardier DHC-8 Series Aeroplanes

CF-2018-21R1 - Wings - Cracked Spoiler Actuator Bracket

Turbine Engines

General Electric Turbine Engines - GE90 Series

2018-20-22 - Combustion Case Replacement

2018-20-23 - HPC Rotor Stage 2-5 Spools