



CASA AD Biweekly 26/2020 – 24 December 2020

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 11 December and 24 December 2020.

Rotorcraft

Airbus Helicopters (Eurocopter) AS 332 Series Helicopters

2020-0281 - Equipment / Furnishings - Hoist Control Power Supply - Modification
2020-0022R2 - Time Limits / Maintenance Checks - Main Gear Box / Particle Detectors - Inspection;
and - Main Rotor Drive - Planet Gear Assemblies - Replacement / Modification

Airbus Helicopters Deutschland (Eurocopter) EC 135 Series Helicopters

2020-0282 - Tail Rotor - Blades - Inspection
2018-0168R1 - Tail Rotor - Blade - Re-identification / Life Limit

Airbus Helicopters (Eurocopter) EC 225 Series Helicopters

2020-0281 - Equipment / Furnishings - Hoist Control Power Supply - Modification

Airbus Helicopters (Eurocopter) SA 360 and SA 365 Series Helicopters

2020-0287 - Tail Rotor Drive - Tail Rotor Drive Flange / Shaft Flexible Coupling - Inspection /
Modification

Below 5700 kgs

Aerostar Aircraft Corporation (Piper / Ted Smith) 600 and 700 Series Aeroplanes

2020-24-10 - Elevator and Aileron Balance Tubes - Inspection / Replacement

Textron Aviation (Beechcraft) 33 and 35-33 (Debonair/Bonanza) Series Aeroplanes

PAD/BEECH 33/41 Amdt 2 - Wing Bolt, Nut and Fitting

Textron Aviation (Beechcraft) 35 (Bonanza) Series Aeroplanes

PAD/BEECH 35/67 Amdt 2 - Wing Bolt, Nut and Fitting

Textron Aviation (Beechcraft) 36 (Bonanza) Series Aeroplanes

PAD/BEECH 36/43 Amdt 2 - Wing Bolt, Nut and Fitting

Textron Aviation (Beechcraft) 55, 58 and 95-55 (Baron) Series Aeroplanes

PAD/BEECH 55/79 Amdt 3 - Wing Bolt, Nut and Fitting

Textron Aviation (Beechcraft) 95 (Travelair) Series Aeroplanes

PAD/BEECH 95/26 Amdt 2 - Wing Attach Fittings, Bolts and Nuts

Above 5700 kgs

Airbus A319, A320 and A321 Series Aeroplanes

2020-0274 - Electrical Power - Nickel-Cadmium Rechargeable Batteries - Replacement
2020-0280 - Fuselage - Skin Above Lap Joint - Inspection

Airbus A330 Series Aeroplanes

2020-0279 - Navigation - Pitot Probe Attachment Nuts - Re-Torque
2020-0283 - Fuel - Fuel Pump - Inspection

Airbus A380 Series Aeroplanes

2020-0276 - Aircraft Flight Manual / Freezing Fog Time Limit - Amendment
2020-0285 - Indicating / Recording Systems - Flight Data Recording System - Modification (Software Update)
2020-0286 - Pneumatic - Pylon / Wing Interface Bleed Duct and Fuel Pipe - Inspection

Boeing 737 Series Aeroplanes

2020-26-04 - Fuselage Skin Panels - Cracking
2020-26-09 - Centre Wing Box - Inspection / Repair

Boeing 747 Series Aeroplanes

2020-21-16 - Upper Wing Skin at Engine Nacelle Attachment Points

Boeing 757 Series Aeroplanes

2020-21-17 - Engine Drag Fitting Joint and Fastener Heads

Boeing 777 Series Aeroplanes

2020-22-10 - Boeing Material Specification (BMS) 8-39 Flexible Urethane Foam - Inspection / Replacement

Boeing 787 Series Aeroplanes

2020-24-04 (Correction) - Autopilot Flight Director System - Flight Manual Amendment
2020-26-08 - Inner Fixed Structure Forward Upper Fire Seal and Thrust Reverser Thermal Insulation Blankets

Bombardier and MHI RJ Aviation CL-600 Series Aeroplanes

CF-2020-54R1 - Landing Gear - Main Landing Gear (MLG) Shock Strut Lower Pin Cracking

Dassault Aviation Falcon 7X Series Aeroplanes

2020-0284 - Equipment / Furnishings - Cabin Seat Pin and Plate - Inspection

Dassault Aviation Mystere-Falcon 50 and 900 and Falcon 900EX Series Aeroplanes

2020-0284 - Equipment / Furnishings - Cabin Seat Pin and Plate - Inspection

Dassault Aviation Falcon 2000 Series Aeroplanes

2020-0284 - Equipment / Furnishings - Cabin Seat Pin and Plate - Inspection

Textron Aviation (Cessna) 560 (Citation V) and 560XL Series Aeroplanes

2020-26-05 - Throttle Quadrant Assembly Sensor Link and Sensor Drive Arm Pivot - Inspection

Piston Engines

Lycoming Engines Piston Engines

2020-25-12 - Superior Air Parts Crankshaft Assembly (P/N) SL36500-A20 & P/N SL36500-A31 - Removal From Service

Superior Air Parts Piston Engines

2020-25-12 - Superior Air Parts Crankshaft Assembly (P/N) SL36500-A20 & P/N SL36500-A31 - Removal From Service

Turbine Engines

General Electric Turbine Engines - GEnx Series

2020-25-10 - High Pressure Turbine Rotor Stage 2 Disk - Inspection / Replacement