

Piper PA 28 Main Landing Gear

**AWB** 32-006      **Issue :** 1  
**Date :** 5 March 2007

## 1. Applicability

All piper PA28 series aircraft with fixed undercarriage.

## 2. Purpose

This AWB is issued to bring to the attention of all registered operators and maintainers of PA28 aircraft with fixed undercarriage that the cast main landing gear strut cylinders may crack.

## 3. Background

A recent SDR has been received indicating that cracks have been found in cast main landing gear strut cylinders.

## 4. Recommendation

All registered operators and maintainers of PA28 aircraft with fixed undercarriage note and act on the content of Piper Service Bulletin 1131.

## 5. Enquiries

Enquiries with regard to the content of this Airworthiness Bulletins should be made via the direct link e-mail address: [AirworthinessBulletin@casa.gov.au](mailto:AirworthinessBulletin@casa.gov.au)

Or in writing, to:

Manufacturing, Certification and  
New Technologies Office,  
GPO Box 2005, Canberra, ACT, 2601