



CASA AD Biweekly 10/2013 – 16 May 2013

The Civil Aviation Safety Authority has published the following Airworthiness Directives between 3 May 2013 and 16 May 2013.

Rotorcraft

Eurocopter EC 225 Series Helicopters

AD/EC 225/5 - Main Rotor Blade Leading Edge Protective Strip - CANCELLED
2013-0103 - Main Rotor - Blade Leading Edge Protective Strip - Check

Below 5700 kgs

Aerospatiale (Socata) TBM 700 Series Aeroplanes

AD/TBM 700/42 - Rivets at Frames C18 BIS and C19 - CANCELLED
2013-0104 - Flight Control - Flap Actuator - Inspection / Replacement

Consolidated Aeronautics, Colonial and LA-4 Series Aeroplanes

2013-08-14 - Horizontal Stabiliser Attachment Fitting

Twin Commander (Gulfstream/Rockwell/Aerocommander 500, 600 and 700) Series Aeroplanes

2013-09-05 - Fuselage Attachment to Main Spar - Inspection and Reinforcement

Above 5700 kgs

Airbus Industrie A319, A320 and A321 Series Aeroplanes

2013-0106 - Equipment / Furnishings - Varnish on Veneered Panels - Inspection / Re-furbishing

AMD Falcon 50 and 900 Series Aeroplanes

2013-0106 - Equipment / Furnishings - Varnish on Veneered Panels - Inspection / Re-furbishing

Boeing 727 Series Aeroplanes

AD/B727/192 - Engine - Reverse Thrust Operating Limitations - CANCELLED
2013-0106 - Equipment / Furnishings - Varnish on Veneered Panels - Inspection / Re-furbishing

Boeing 737 Series Aeroplanes

2012-18-13R1 - Fatigue Cracks - Aft Pressure Bulkhead - Inspection
2013-08-01 - Thrust Reverser Upper Fire Seals - Inspection
2013-09-01 - Fuselage Lap Joints
2013-09-02 - Flap Track Assembly and Rear Spar Attachments
2013-0106 - Equipment / Furnishings - Varnish on Veneered Panels - Inspection / Re-furbishing
2013-09-08 - Fuel System - Engine Fuel Suction Feed

Bombardier BD-700 Series Aeroplanes

2013-0106 - Equipment / Furnishings - Varnish on Veneered Panels - Inspection / Re-furbishing

Bombardier (Canadair) CL-600 (Challenger) Series Aeroplanes

2013-0106 - Equipment / Furnishings - Varnish on Veneered Panels - Inspection / Re-furbishing
CF-2013-12 - Rudder Control System - Cracking of the Pilot-Side Rudder Pedal Tubes

British Aerospace BAe 146 Series Aeroplanes

2013-0106 - Equipment / Furnishings - Varnish on Veneered Panels - Inspection / Re-furbishing

Dassault Aviation Falcon 2000 Series Aeroplanes

2013-0106 - Equipment / Furnishings - Varnish on Veneered Panels - Inspection / Re-furbishing

Fokker F28 Series Aeroplanes

2013-0102 - Fuselage - Centre Fuselage - Modification

Fokker F100 (F28 Mk 100) Series Aeroplanes

2013-0102 - Fuselage - Centre Fuselage - Modification

Gulfstream Aerospace G150 Series Aeroplanes

24-07-10-11 - Left Electrical DC Power Box - Inspection and Relocation of Feeder Cable
01-12-02-02 - Aircraft Flight Manual (AFM) - Update
25-04-05-09R1 - Baggage Compartment - Rubber Seals - Replacement

Gulfstream (Grumman) G1159, G-IV and GV Series Aeroplanes

2013-0106 - Equipment / Furnishings - Varnish on Veneered Panels - Inspection / Re-furbishing

Turbine Engines

General Electric Turbine Engines - CF6 Series

AD/CF6/45 - Fuel Tube Replacement - CANCELLED

Rolls Royce Turbine Engines - RB211 TRENT 900 Series

2012-0220R1 - Engine - Low Pressure Turbine Disc Seal Fins and Interstage Seals - Inspection / Replacement